



Technical Memorandum

1100 – 112th Ave NE, Suite 500
Bellevue, WA 98004
425.453.5000

Subject Lake Whatcom Tunnel Condition Assessment Report (Task 5.2) (Final)

Project Name Raw Water Intake Condition Assessment and Intertie Pipeline Design

Attention Steve Day, PE / Project Manager for City of Bellingham

From Robert Martin, PE / Jacobs
Phil Martinez, PE / Jacobs
Kenny Moffat, PE / Jacobs

Date June 14, 2024

Contents of Memorandum

| | |
|--|----|
| 1. Introduction..... | 2 |
| 2. Description of Tunnel..... | 2 |
| 3. Summary of Prior Inspections..... | 4 |
| 4. Field Inspection Methods and Approach..... | 5 |
| 4.1 Defect Coding, Scoring, and Rehabilitation Priority..... | 5 |
| 4.2 Inspection Plan and Safety | 5 |
| 4.3 Tunnel Stationing | 6 |
| 5. Inspection Results..... | 6 |
| 6. Summary of Key Results..... | 9 |
| 7. Recommendations for Next Steps..... | 11 |
| 7.1 Non-Destructive Investigation of Structural Defects..... | 12 |
| 7.2 Develop Alternative Water Intake Strategy..... | 12 |
| 7.3 Invasive Investigation of Suspected Voids and Longitudinal Cracks..... | 13 |
| 7.4 Repair Structural Defects..... | 13 |
| 8. Representative Photos..... | 14 |
| 8.1 Structural Defects..... | 14 |
| 8.2 Operational Defects..... | 18 |

Attachments:

- A. Lake Whatcom Tunnel Drawings
- B. Defect Coding, Scoring, and Rehabilitation Priority
- C. Inspection Plan
- D. Lake Whatcom Tunnel Defect Distribution
- E. Summary of Location of Holes and Voids Contributing to High Priority Rating
- F. Tunnel Inspection Report Notes

1. Introduction

This condition assessment report documents the March 2024 Lake Whatcom Raw Water Tunnel (tunnel) condition assessment. The tunnel and overall raw water conveyance system is owned by the City of Bellingham. The tunnel extends on its upstream end from the Gatehouse on the shore of Lake Whatcom to the Screenhouse on the downstream end where traveling screens remove debris from the flow stream that is conveyed downstream to the Whatcom Falls Water Treatment Plant (WTP).

The City of Bellingham (City) completed assessments of the tunnel on four previous occasions starting with the first inspection in 1988, 1990, 2012, 2014, and 2015. A summary and assessment of the 1988, 1990, 2012, and 2014 inspections are presented in the Draft July 2015 Lake Whatcom Tunnel Condition Assessment (CH2M HILL). This 2015 report was never revised or finalized, but it comprises a robust documentation of work completed prior to March 2024 inspection. The results presented herein enable direct comparison to the results of the 2015 condition assessment work.

2. Description of Tunnel

The Lake Whatcom Raw Water Tunnel is located in Bellingham Washington, extending from Lake Whatcom to the City's Screenhouse, as shown in Figure 1. It is a horseshoe-shaped tunnel constructed in 1939 with a length of 7,560 linear feet (LF) and a diameter of 6.5 ft. It has a capacity of approximately 100 million gallons per day (mgd). It appears the tunnel was constructed using drill and blast methods. It is fitted with a cast-in-place concrete lining. The tunnel conveys raw water from the upstream Gatehouse on the west shore of Lake Whatcom to the downstream Screenhouse in Whatcom Falls Park. A summary of the tunnel design is presented in Table 1.

Up until the closure of the Georgia Pacific Pulp and Paper Mill, which occurred over time between 2001 and 2007, the tunnel conveyed in excess of 50 mgd at times and regularly conveyed over 30 mgd for decades. Currently, flow through the tunnel is primarily to serve the City's municipal needs, which range from peak daily usage of 20 mgd to an average daily usage of 10 mgd. Other average daily water usage through the tunnel includes approximately 1 mgd associated with the downstream Puget Sound Energy Cogeneration power generating facility. Additionally, there is "return flow," estimated to be 5 mgd, from the upstream side of the traveling screens in the Screenhouse to Whatcom Creek. The resulting current average daily flow through the tunnel is approximately 16 mgd, which equates to a tunnel velocity of approximately 1 foot per second.

Two photographs each of the Gatehouse and Screenhouse are presented as Exhibits 1 and 2, respectively. Drawings from the original design and construction of the tunnel are presented in Attachment A. These drawings include a plan and profile, typical sections, tunnel details, shaft structure design details, geologic information, and progress chart from the original tunnel construction showing the geology encountered along the alignment.

FIGURE 1
Alignment of Lake Whatcom Raw Water Tunnel




TABLE 1
Lake Whatcom Raw Water Tunnel Design Summary

| Parameter | Description |
|-----------------------------------|---|
| Designer | Baar and Cunningham |
| Contractor | B.H Sheldon (Tunnel Contractor) |
| Construction Completed | 1939 |
| Tunnel length | 7,560 feet (1.4 miles) |
| Upstream Elevation | 298.5 feet |
| Downstream Elevation | 290.94 feet |
| Tunnel slope | 0.1% |
| Cross section per plan | Horseshoe; 5.0 feet bottom width x 6.25 feet high |
| Cross section (lined) as observed | Horseshoe; 6.3 feet Spring line width x 6.5 feet high |

Lake Whatcom Tunnel Condition Assessment Report


EXHIBIT 1

Screenhouse (Downstream End of Tunnel)



EXHIBIT 2

Gatehouse (Upstream End of Tunnel) and Slide Gate Stem



3. Summary of Prior Inspections

Prior to the March 2024 inspection, the tunnel was formally inspected on four separate occasions. Documentation on these prior inspections is presented in the 2015 Condition Assessment Report: Lake Whatcom Tunnel Condition Assessment Report (Task 2.3.3), July 2015, CH2M HILL. For reference, these prior reports are listed below:

- 1988 Tunnel Liner Observation and Preliminary Geotechnical Engineering Assessment, Hart Crowser
- 1990 Geotechnical Engineering Assessment, Tunnel Observations, Repairs, Tests and Exploratory Work, Hart Crowser
- 2012 ROV Inspection Report, iPi: Laser scanning data (discussed further below); ROV camera inspection video; Support diver helmet camera video

- 2014 City of Bellingham Lake Whatcom Tunnel: Preliminary Condition Assessment and Improvement Report (Task 2.2.2), November 7, 2014, CH2M HILL
- 2015 Condition Assessment Report: Lake Whatcom Tunnel Condition Assessment Report (Task 2.3.3), July 2015, CH2M HILL

Review of the reports summarizing the prior inspection and condition assessment efforts aided the work planning for the March 2024 tunnel inspection.

4. Field Inspection Methods and Approach

The inspection of the tunnel liner was completed on March 20, 2024 in conformance with industry accepted practices and standards. The inspection approach implemented was based on practices and standards defined by the National Association of Sewer Service Companies (NASSCO) Pipe Assessment Condition Program (PACP) for small diameter pipelines. These practices and standards were modified for the Lake Whatcom tunnel inspection, reflecting Jacobs' standard approach, as there are no similar defined condition assessment standards for large diameter tunnels in the US.

4.1 Defect Coding, Scoring, and Rehabilitation Priority

Defect terminology, associated defect codes, and concrete liner rating used during the field inspection is presented in Attachment B. Also presented in Attachment B, are associated rehabilitation priorities associated with the defect scoring. An understanding of the defect coding, liner rating values, and rehabilitation priority presented in Attachment B is necessary to understand the inspection results presented in Section 5.

The standard inspection defect coding used for this project is grouped into three main categories: structural, operational, and other.

Structural defects consist of the fractures, cracks, collapse, breaks, and surface damage. Definitions of the structural codes used for this inspection are presented in Attachment B. Operational defects include debris, deposits, protruding structures, and infiltration. Definitions of the operational codes used for this inspection are presented in Attachment B. Codes characterized as "other" consist of construction features and miscellaneous observations that typically do not require rehabilitation or renewal activities.

Each 100-foot length of the concrete liner of the tunnel (from station to station) was rated or "scored" with respect to defects in conformance with the rating methodology presented in Attachment B. The priority for rehabilitation of each of the 100-foot lengths was then developed based on the NASSCO standardized approach. While operational and other defects are included in the condition rating, the frequency and severity of structural defects is typically driver of the overall condition rating and corresponding rehabilitation prioritization.

4.2 Inspection Plan and Safety

The *Inspection Plan for Lake Whatcom Screenhouse, Tunnel and Gatehouse, dated February 2024* included in Attachment C was prepared to guide the tunnel inspection, which was completed over the course of a single day between the hours of 9:00 am to 4:30 pm.

The tunnel was entered under confined space entry safety procedures in conformance with a tunnel entry safety plan that was developed under separate cover. Life Rescue, Inc provided safety support for the tunnel entrants based on the safety plan. A pre-entry safety coordination meeting was conducted the morning prior to the tunnel entry. Confined space entry attendants were stationed at the upstream, intermediate, and downstream tunnel access points (two at each; 6 total plus one supervisor). An air

monitor was present at each access point and the inspection teams were equipped with air monitors, as well. Jacobs' safety manager was present on site throughout the day to serve as the overall safety lead for the tunnel entry.

Air flow through the tunnel was enhanced using a 10,000 cfm blower at the Gatehouse opening. The blower system appeared to provide more than adequate ventilation. In alignment with the inspection plan, air monitoring checks were performed at each access point prior to the blower being turned on to document background conditions. The background conditions were found to not exceed any limits on the 5-gas monitor.

As the inspection team neared the Gatehouse, as they completed the inspection, the blower was turned off. Even after the blower was turned off there was noticeable air flow through the tunnel. Even during this time air quality was measured continually. Oxygen levels remained above 20.5 percent and no detection of carbon monoxide; hydrogen sulfide; nor methane was noted at any time during the course of the inspection, consistent with the background readings prior to inspection activities and use of the blower.

4.3 Tunnel Stationing

During the previous inspection (2015) permanent markers were placed every 100 feet on the south side of the tunnel to aid location of inspection documentation and to aid future inspections. The permanent markers consist of an aluminum washer stamped with the year "2015" and the corresponding station number, as shown in Exhibit 3. Washers were affixed to stainless steel friction anchors that were pounded into holes drilled with a rotary hammer drill. All markers were intact and, while experiencing some corrosion, were generally legible when observed through the course of completing the 2024 inspection.

EXHIBIT 3

Permanent Station Markers Installed in the Tunnel



5. Inspection Results

Key results of the March 2024 inspection of the concrete tunnel liner along with a comparison of ratings to the previous 2015 inspection are presented in Table 2. The liner rating was computed, and the rehabilitation priority developed on a per-100-foot section based on the methodology presented in Attachment B. The major defect types contributing to the "high" rehabilitation priority are presented in Table 2 and factors that contributed to a change in rating. The changes in rehabilitation priority rows are

highlighted. A graphical representation of the rehabilitation priority changes is presented in Attachment D. In addition to presenting distribution of rehabilitation priority along the tunnel, the figure in Attachment D presents the location of tunnel defects with a score or weighting of 4, the highest severity observed (no tunnel defects with a score of 5 were observed). New defects identified as part of the March 2024 inspection are presented in RED.

As noted in Table 2, the vast majority of the major defects that impact rehabilitation priority are holes and longitudinal fractures. Holes and longitudinal fractures in the liner are of particular concern because they often indicate the presence of voids behind the concrete liner. Voids are a major concern because they typically form from the migration of material outside of the tunnel liner. Small voids are not as much of a concern as are larger voids. But voids can change shape and grow over time. When this happens, these voids prevent the even-distribution of support from the surrounding sub-surface. Stress concentrations on the liner can result in damage or failure to the liner, which can result in even greater damage outside and/or above the tunnel – potentially extending to the surface. Consequently, because of their potential criticality, the specific locations of hole and longitudinal fracture defects observed during the inspection are presented in the table in Attachment E so that these areas can be target in future investigations.

The specific defects contributing to the “low” and “medium” rehabilitation priority are not presented in Table 2, but instead can be reviewed in the detailed tunnel inspection report notes included in Attachment F. These tunnel inspection report notes present descriptions of each of the tunnel liner defects, as observed in the field. The tunnel inspection report notes presented in Attachment F are comprised of the 2015 inspection report notes with updates as applicable for each defect. This approach ensured that all of the defects observed in 2015 were re-inspected and that the differences are clearly identified. These differences, as well as newly observed defects in 2024, are identified in red text within Attachment F.

Table 2

Tunnel Liner Rating, Rehabilitation Priority, and Defects Per 100 foot Tunnel Segment

| Start Station | End Station | Concrete Tunnel Liner Rating (2015) | Concrete Tunnel Liner Rating (2024) | Rehabilitation Priority | Major Defect Noted |
|---------------|-------------|-------------------------------------|-------------------------------------|-------------------------|-----------------------|
| 0+00 | 1+00 | 2 | 2 | Low | Refer to Attachment F |
| 1+00 | 2+00 | 2 | 2 | Low | Refer to Attachment F |
| 2+00 | 3+00 | 3 | 3 | Medium | Refer to Attachment F |
| 3+00 | 4+00 | 3 | 3 | Medium | Refer to Attachment F |
| 4+00 | 5+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 5+00 | 6+00 | 2 | 2 | Low | Refer to Attachment F |
| 6+00 | 7+00 | 0 | 4 | High | Fracture Longitudinal |
| 7+00 | 8+00 | 3 | 3 | Medium | Refer to Attachment F |
| 8+00 | 9+00 | 3 | 3 | Medium | Refer to Attachment F |
| 9+00 | 10+00 | 3 | 3 | Medium | Refer to Attachment F |
| 10+00 | 11+00 | 3 | 3 | Medium | Refer to Attachment F |
| 11+00 | 12+00 | 3 | 3 | Medium | Refer to Attachment F |
| 12+00 | 13+00 | 3 | 3 | Medium | Refer to Attachment F |
| 13+00 | 14+00 | 3 | 3 | Medium | Refer to Attachment F |
| 14+00 | 15+00 | 3 | 3 | Medium | Refer to Attachment F |
| 15+00 | 16+00 | 3 | 3 | Medium | Refer to Attachment F |
| 16+00 | 17+00 | 4 | 4 | High | Hole Void Visible |
| 17+00 | 18+00 | 4 | 4 | High | Fracture Longitudinal |
| 18+00 | 19+00 | 3 | 3 | Medium | Refer to Attachment F |
| 19+00 | 20+00 | 3 | 3 | Medium | Refer to Attachment F |
| 20+00 | 21+00 | 4 | 4 | High | Hole Void Visible |
| 21+00 | 22+00 | 4 | 4 | High | Fracture Longitudinal |

Lake Whatcom Tunnel Condition Assessment Report

| Start Station | End Station | Concrete Tunnel Liner Rating (2015) | Concrete Tunnel Liner Rating (2024) | Rehabilitation Priority | Major Defect Noted |
|---------------|-------------|-------------------------------------|-------------------------------------|-------------------------|-----------------------|
| 22+00 | 23+00 | 3 | 4 | High | Fracture Longitudinal |
| 23+00 | 24+00 | 4 | 4 | High | Fracture Longitudinal |
| 24+00 | 25+00 | 3 | 3 | Medium | Refer to Attachment F |
| 25+00 | 26+00 | 3 | 3 | Medium | Refer to Attachment F |
| 26+00 | 27+00 | 3 | 3 | Medium | Refer to Attachment F |
| 27+00 | 28+00 | 4 | 4 | High | Hole Void Visible |
| 28+00 | 29+00 | 3 | 3 | Medium | Refer to Attachment F |
| 29+00 | 30+00 | 3 | 3 | Medium | Refer to Attachment F |
| 30+00 | 31+00 | 3 | 3 | Medium | Refer to Attachment F |
| 31+00 | 32+00 | 3 | 3 | Medium | Refer to Attachment F |
| 32+00 | 33+00 | 4 | 4 | High | Hole Void Visible |
| 33+00 | 34+00 | 3 | 3 | Medium | Refer to Attachment F |
| 34+00 | 35+00 | 4 | 4 | High | Hole Void Visible |
| 35+00 | 36+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 36+00 | 37+00 | 3 | 3 | Medium | Refer to Attachment F |
| 37+00 | 38+00 | 1 | 1 | Not Required | Refer to Attachment F |
| 38+00 | 39+00 | 4 | 4 | High | Hole Void Visible |
| 39+00 | 40+00 | 2 | 3 | Medium | Fracture Longitudinal |
| 40+00 | 41+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 41+00 | 42+00 | 4 | 4 | High | Fracture Longitudinal |
| 42+00 | 43+00 | 3 | 3 | Medium | Refer to Attachment F |
| 43+00 | 44+00 | 3 | 3 | Medium | Refer to Attachment F |
| 44+00 | 45+00 | 2 | 2 | Low | Refer to Attachment F |
| 45+00 | 46+00 | 3 | 3 | Medium | Refer to Attachment F |
| 46+00 | 47+00 | 3 | 3 | Medium | Refer to Attachment F |
| 47+00 | 48+00 | 4 | 4 | High | Hole Void Visible |
| 48+00 | 49+00 | 3 | 3 | Medium | Refer to Attachment F |
| 49+00 | 50+00 | 4 | 4 | High | Hole Void Visible |
| 50+00 | 51+00 | 4 | 4 | High | Hole Soil Visible |
| 51+00 | 52+00 | 3 | 3 | Medium | Refer to Attachment F |
| 52+00 | 53+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 53+00 | 54+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 54+00 | 55+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 55+00 | 56+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 56+00 | 57+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 57+00 | 58+00 | 4 | 4 | High | Hole Void Visible |
| 58+00 | 59+00 | 4 | 4 | High | Hole Soil Visible |
| 59+00 | 60+00 | 4 | 4 | High | Hole Void Visible |
| 60+00 | 61+00 | 4 | 4 | High | Fracture Longitudinal |
| 61+00 | 62+00 | 3 | 3 | Medium | Refer to Attachment F |
| 62+00 | 63+00 | 4 | 4 | High | Hole Void Visible |
| 63+00 | 64+00 | 4 | 4 | High | Hole Soil Visible |
| 64+00 | 65+00 | 4 | 4 | High | Hole Soil Visible |

| Start Station | End Station | Concrete Tunnel Liner Rating (2015) | Concrete Tunnel Liner Rating (2024) | Rehabilitation Priority | Major Defect Noted |
|---------------|-------------|-------------------------------------|-------------------------------------|-------------------------|-----------------------|
| 65+00 | 66+00 | 3 | 3 | Medium | Refer to Attachment F |
| 66+00 | 67+00 | 2 | 2 | Low | Refer to Attachment F |
| 67+00 | 68+00 | 4 | 4 | High | Hole Void Visible |
| 68+00 | 69+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 69+00 | 70+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 70+00 | 71+00 | 0 | 0 | Not Required | Refer to Attachment F |
| 71+00 | 72+00 | 4 | 4 | High | Hole Soil Visible |
| 72+00 | 73+00 | 3 | 3 | Medium | Refer to Attachment F |
| 73+00 | 74+00 | 2 | 2 | Low | Refer to Attachment F |
| 74+00 | 75+00 | 0 | 3 | Medium | Fracture Longitudinal |
| 75+00 | 76+00 | 2 | 2 | Low | Refer to Attachment F |

Note: 100-foot segments showing a change in priority rating from 2015 to 2024 are highlighted in blue.

6. Summary of Key Results

In general, the Lake Whatcom Raw Water tunnel liner is in fair condition and appears to be stable. In 2015 seventy-one (71) percent of the tunnel has a rehabilitation priority of "Not Required" to "Medium" (liner rating levels of 0 to 3). In 2024 sixty-two (62) percent of the tunnel has a rehabilitation priority of "Not Required" to "Medium" (liner rating levels of 0 to 3) resulting in a degradation of the tunnel of nine (9) percent. These portions of the tunnel require further monitoring and repairs that should be implemented within 5 to 10 years.

In 2015 twenty nine (29) percent of the tunnel was assigned a rehabilitation priority of "High" (liner rating level of 4). In 2024 thirty-eight (38) percent of the tunnel was assigned a rehabilitation priority of "High" (liner rating level of 4). These portions of the tunnel warrant repairs within one year to prevent the damage associated with these defects from further degradation of the tunnel. No sections of the tunnel were given a rehabilitation priority of "Immediate" (liner rating level of 5).

As presented in the table in Attachment E, a total of 52 locations within the tunnel were identified as either a hole with a visible void (Hole Void Visible) or a hole with visible migration of soil (Hole Soil Visible) in 2015. In 2024 a total of 56 locations within the tunnel were identified as either a hole with a visible void or a hole with visible migration of soil.

A particularly large void was observed behind the liner at station 75+11 to 75+14. In 2015, the void appeared to be approximately 3-feet in diameter and at least 7-inches deep, but may have extended further. When this location was revisited during the 2024 inspection, the liner was still intact over the void and does not appear to have grown over the last 10 years.

In 2015, 103 locations with longitudinal fracturing of the concrete tunnel liner were identified. In 2024, 115 locations with longitudinal fracturing of the concrete tunnel liner were identified. Five of these fractures had offsets of up to 0.19 inches during the 2015 inspection, which were observed to be up to 0.22 inches during the 2024 inspection as presented in Exhibit 4. Longitudinal fracturing is a significant structural defect that suggests the lack of support between the liner and the excavated surface. The importance of these fractures is dependent on the extent to which there is change in their size and offset. In this instance there is evidence of movement of the liner suggesting external pressure is displacing the concrete liner.

There were several tunnel liner locations (5+47 to 5+49, 30+45, 33+01 to 33+02, and 33+06 to 33+07) where the liner was thin or deteriorating to a point where the concrete could easily be scraped away at the surface. One notable example of this deterioration is presented in Exhibit 6 showing a comparison from 2015 to 2024 where the liner has continued to move approximately 0.06 inches since 2015.

EXHIBIT 4

Offset Longitudinal Fracture in Tunnel Liner Comparison from 2015 on the left to 2024 on the right



EXHIBIT 5

Typical Holes Found in the Tunnel Liner



EXHIBIT 6

Deteriorated Concrete Tunnel Liner from 2015 on the left to 2024 on the right



7. Recommendations for Next Steps

As stated above, the Lake Whatcom tunnel is generally in fair condition, able to continue providing beneficial service to the City; however, capital expenditure to keep it in a useful condition is warranted, evidenced by the degradation of almost 10 percent in 10 years since the prior inspection. Although the tunnel has provided relatively minimal- to low-cost service for over 80 years, rehabilitation of the tunnel is necessary and regular monitoring is essential to extend its useful life. Replacement of the tunnel would far exceed the cost of rehabilitation. Action to rehabilitate the tunnel should be implemented as a high priority.

The structural defects (holes and fractures) observed in the liner and voids that may be present behind the liner wall represent the greatest threats to the integrity and continued use of the tunnel. These structural defects contributed to almost 40 percent of the liner receiving a "High" rehabilitation priority. A concrete tunnel liner rating of 4 corresponds with a recommended repair implementation within the next year. It is understood that repairs are likely not feasible within the next year, or even the next two or three years, because the tunnel cannot be removed from service for an extended period of time. That stated, actions to address these "High" priority defects should be initiated as soon as practical.

Specific recommendations presented in the sections below relate to:

- **Non-Destructive Investigation of Structural Defects.** This effort is necessary to improve understanding of specific structural defects that are a threat to the integrity of the concrete tunnel liner.
- **Develop Alternative Intake Strategy.** Identification of an alternative supply source to allow for extended tunnel outage (several months) will enable effective repair of defects in the tunnel. Without an extended period where there is no water flow through the tunnel, the effective repair of voids is likely not feasible.
- **Invasive Investigation of Suspected Voids and Longitudinal Cracks.** Following implementation of alternative intake strategy perform thorough investigations, which may include coring of the concrete liner and behind the liner, to improve understanding of void presence and extents, as well as the driver for longitudinal cracks.
- **Repair Structural Defects.** Following implementation of alternative intake strategy and further evaluation of voids behind the concrete liner, implement structural repairs of voids behind the liner and surficial defects within the liner itself.

7.1 Non-Destructive Investigation of Structural Defects

The initial goal is to identify and characterize void presence behind the cast-in-place liner. An attempt should be made within the next year using non-destructive testing methods such as handheld ground penetrating radar (GPR) or pull along GPR units. The initial attempt at characterizing of voids can be accomplished during a single, "24-hr" single shutdown event, similar to the March 20, 2024, inspection event, with the radar-inspection team being in the tunnel for a period of up to 12 hours. Scanning would be targeted at structural defect locations with defect weight of 4 or greater. But it is anticipated that several thousand feet of the tunnel could be radar-inspected during this single event. Subsequent radar-inspections could be implemented, if warranted, depending on the results and success of the initial radar-inspection. For budgeting purposes, considering the involvement of the tunnel consultant, radar technician(s), a professional extraction safety team, and associated planning and report documentation, the estimated cost would be \$100,000, not including City-staff time.

7.2 Develop Alternative Water Intake Strategy

To effectively implement rehabilitation of the tunnel liner to correct structural defects, it will be necessary for the tunnel to be taken out of service for an extended period of time. Currently, it's not possible to have access to the tunnel for more than approximately 24 continuous hours at any given time. This is because the tunnel is the sole means of getting water from Lake Whatcom to the City's Whatcom Falls Water Treatment Plant. Without being able to take the tunnel out of service for an extended period of time, investigating and repairing holes and voids would require many short shut downs of the tunnel. Such short shutdowns may be able to accommodate investigation, but likely not repairs. It is understood the City is planning its consideration of alternatives for a secondary means of getting water from Lake Whatcom to its WTP.

In addition to developing an alternative water intake strategy to take the tunnel out of service, the leakage through the slide gate in the Gatehouse will need to be reduced, if not eliminated. Reducing or eliminating leakage could be done via slide gate replacement, which is already being contemplated by the City. Other methods for addressing leakage could be considered, such as removing corrosion product or other means of plugging the gaps between the slide gate and gate frame. Refer to Exhibit 7 below for the slide gate leakage observed during the March 2024 tunnel inspection.

EXHIBIT 7**Seepage through Gate at Gatehouse (Non- PACP code)**

7.3 Invasive Investigation of Suspected Voids and Longitudinal Cracks

Once an alternative water intake supply is in-place and there is time for construction crews to spend prolonged periods within the tunnel of up to several weeks or months, more in-depth (and invasive) investigative techniques may be deployed to better understand the nature of structural defects behind the liner. Concrete coring may be performed at void locations identified as part of the non-destructive GPR scanning or at notable locations experiencing longitudinal fracturing. At locations with fractures, the rock sample should be characterized and tested for swell potential. Additionally, crack gauges may be deployed at specific locations to track any changes over time to fracture offset.

7.4 Repair Structural Defects

As noted above, there were 56 locations in the tunnel liner where holes were identified. Left unrepaired, these holes will allow for the continued migration of fine grained material and the growth of voids behind the concrete tunnel liner. The result could be instability of the liner and potentially collapse.

Following completion of the preceding recommended investigative and alternative supply actions, repairs to address structural defects in the liner and voids behind the line can be implemented. Quantification and scoping of these repairs can be completed after the invasive investigations described above are completed.

8. Representative Photos

During the course of the March 2024 tunnel inspection various structural and operational defects (as defined within Subsection 4.1) were observed and are shown below.

8.1 Structural Defects

The following subsection presents representative structural defects observed during the tunnel inspection.

EXHIBIT 8

Fracture Multiple (Approx Sta 50+90 @ 3 o'clock position in pipe)




EXHIBIT 9

Hole Soil Visible (Approx Sta 51+10 @ 5 o'clock position in pipe)



Lake Whatcom Tunnel Condition Assessment Report


EXHIBIT 10

Hole Soil Visible (Approx Sta 53+40 @ 5 o'clock position in pipe)



EXHIBIT 11

Hole Soil Visible (Approx Sta 59+60 @ 7 o'clock position in pipe)



8.2 Operational Defects

The following subsection presents representative operational defects observed during the tunnel inspection.

EXHIBIT 12


Infiltration Runner Barrel @ 4 o'clock position in pipe




EXHIBIT 13
Infiltration Runner Barrel (Multiple) @ 12 o'clock position in pipe




Attachment A
Lake Whatcom Tunnel Drawings




WA-38









OFFICE OF CITY ENGINEER
BELLINGHAM, WASH.
LOCATION MAP OF
Lake Whatcom
Water Tunnel

FROM WATKINS POINT
TO WHATCOM FALLS PARK

TO WHATCOM FALLS PARK

SCALE 1:100' FEB. 9, 1940
SW 222-24 - 2011 - ENCLERTE

E.W.GOOCH, CITY ENGINEER

DESIGN BY SHEET 3 OF 3 SHEET

DESIGN BY SHEET 3 OF 3 SHEET
DRAWN BY

DRAWN BY *O.E.S.*
TRACED BY *O.E.S.*

SEARCHED BY C.R.C.

11. *What is the name of the author of the book you are reading?*

Digitized by srujanika@gmail.com

1148 551

WA-56

WA-38

www.ijerph.org

WA-56

A-5-8-13

350 days \$21,000 R.G.Clifford San Francisco
 430 days \$30,000 Marzian-Hudson Co.
 430 days \$30,000 Baileys Idaho
 No time set L.Romanos Seattle, Wash.
 450 days \$18,500 Milder Bellingham, Wash.
 450 days \$22,000 Macri Bros. Seattle, Wash.
 365 days \$17,000 B.H. Sheldon
 540 days \$25,000 Sam Orino Portland, Oregon
 450 days \$35,000 Utah Const. Co. San Francisco
 540 days \$19,500 Crox & Litch Co. Belligham, Wash.

| No | Item | Amount | Unit Price | Total | Unit Price | Total |
|----|---|----------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|-------|
| 1 | Clearing at Portals & Dumps | 2 Acres | 200 00 | 400 00 | 400 00 | 800 00 | 500 00 | 1,000 00 | 300 00 | 600 00 | 500 00 | 1,000 00 | 100 00 | 200 00 | 400 00 | 800 00 | 175 00 | 350 00 | 200 00 | 400 00 | | |
| 2 | Shaft excavation | 350 Cu.yds. | 9 00 | 3,150 00 | 12 00 | 4,200 00 | 40 00 | 14,000 00 | 8 00 | 2,800 00 | 10 00 | 3,500 00 | 6 00 | 2,100 00 | 12 00 | 4,200 00 | 17 25 | 6,037 50 | 8 00 | 2,800 00 | | |
| 3 | Shaft Timbering | 20 MBM. | 60 00 | 1,200 00 | 100 00 | 2,000 00 | 150 00 | 3,000 00 | 50 00 | 1,000 00 | 50 00 | 1,000 00 | 50 00 | 1,000 00 | 90 00 | 1,800 00 | 80 00 | 1,600 00 | 50 00 | 1,000 00 | | |
| 4 | Portal trench excavation | 2,200 Cu.yds. | 2 00 | 4,400 00 | 1 25 | 2,750 00 | 10 00 | 22,000 00 | 1 25 | 2,750 00 | 2 50 | 5,500 00 | 1 00 | 2,200 00 | 1 00 | 2,200 00 | 3 50 | 7,700 00 | 3 00 | 6,600 00 | | |
| 5 | Portal trench timbering | 23 MBM. | 50 00 | 1,150 00 | 75 00 | 1,725 00 | 50 00 | 1,500 00 | 40 00 | 950 00 | 50 00 | 1,150 00 | 50 00 | 1,150 00 | 90 00 | 2,070 00 | 57 50 | 1,322 50 | 40 00 | 920 00 | | |
| 6 | Drainage trench excava. + backfill | 500 Cu.yds. | 2 00 | 1,100 00 | 5 00 | 2,500 00 | 10 00 | 5,000 00 | 5 00 | 2,500 00 | 3 00 | 1,500 00 | 8 00 | 4,000 00 | 1 50 | 750 00 | 3 50 | 1,750 00 | 2 00 | 1,000 00 | | |
| 7 | 18" Sewer pipe drain | 360 lin.ft. | 2 25 | 810 00 | 2 10 | 756 00 | 5 00 | 1,800 00 | 2 00 | 720 00 | 2 50 | 900 00 | 2 25 | 810 00 | 3 00 | 1,080 00 | 1 25 | 630 00 | 2 35 | 846 00 | | |
| 8 | 21" Sewer pipe drain (Alternate) | 360 lin.ft. | 3 00 | 1,080 00 | 3 00 | 1,080 00 | 6 00 | 2,160 00 | 2 50 | 936 00 | 3 00 | 1,000 00 | 2 50 | 900 00 | 4 00 | 1,440 00 | 2 30 | 828 00 | 3 50 | 1,260 00 | | |
| 9 | 24" Sewer pipe drain (Alternate) | 360 lin.ft. | 4 00 | 1,440 00 | 3 60 | 1,296 00 | 7 00 | 2,520 00 | 3 25 | 1,170 00 | 4 00 | 1,440 00 | 3 00 | 1,080 00 | 5 00 | 1,800 00 | 3 00 | 1,080 00 | 3 25 | 1,422 00 | | |
| 10 | Lumber in Bridge | 4 MBM. | 150 00 | 600 00 | 100 00 | 400 00 | 50 00 | 200 00 | 50 00 | 200 00 | 65 00 | 260 00 | 50 00 | 200 00 | 90 00 | 360 00 | 115 00 | 460 00 | 50 00 | 200 00 | | |
| 11 | Tunnel Section "A" | 1400 lin.ft. | 30 75 | 43,050 00 | 30 00 | 42,000 00 | 40 00 | 56,000 00 | 25 00 | 35,000 00 | 27 00 | 37,800 00 | 21 00 | 29,400 00 | 25 00 | 35,000 00 | 40 00 | 56,980 00 | 20 00 | 28,000 00 | | |
| 12 | Temporary timbering Sec. "A" | 15 MBM. | 30 00 | 450 00 | 60 00 | 900 00 | 200 00 | 3,000 00 | 50 00 | 750 00 | 45 00 | 675 00 | 50 00 | 750 00 | 90 00 | 1,550 00 | 80 00 | 1,200 00 | 60 00 | 900 00 | | |
| 13 | Tunnel Section "B" | 6,160 lin.ft. | 30 75 | 189,420 00 | 35 00 | 215,600 00 | 40 00 | 246,400 00 | 25 00 | 154,000 00 | 27 00 | 166,320 00 | 16 00 | 98,560 00 | 25 00 | 154,000 00 | 44 00 | 276,276 00 | 18 00 | 110,880 00 | | |
| 14 | Steel Sets Section "B" | 216,000 lbs. | .06 | 12,960 00 | .10 | 21,600 00 | .10 | 21,600 00 | .10 | 21,000 00 | .10 | 21,600 00 | .08 | 17,280 00 | .10 | 21,600 00 | .15 | 24,940 00 | .10 | 21,600 00 | | |
| 15 | Logging etc. Section "B" | 245 MBM. | 30 00 | 7,350 00 | 60 00 | 14,700 00 | 100 00 | 24,500 00 | 50 00 | 12,250 00 | 45 00 | 11,025 00 | 50 00 | 12,250 00 | 90 00 | 22,050 00 | 104 00 | 25,480 00 | 60 00 | 14,700 00 | | |
| 16 | Tunnel Section "C" (Alternate) | 6,160 lin.ft. | 30 75 | 189,420 00 | 36 00 | 221,760 00 | 40 00 | 246,400 00 | 25 00 | 154,000 00 | 28 00 | 172,480 00 | 17 00 | 104,720 00 | 25 00 | 154,000 00 | 48 30 | 297,520 00 | 21 00 | 129,360 00 | | |
| 17 | Timbering Section "C" (Alternate) | 385 MBM. | 50 00 | 19,250 00 | 80 00 | 30,800 00 | 125 00 | 48,125 00 | 50 00 | 19,250 00 | 55 00 | 21,175 00 | 50 00 | 19,250 00 | 90 00 | 34,650 00 | 92 00 | 35,420 00 | 65 00 | 25,025 00 | | |
| 18 | Tunnel Section "D" (Alternate) | 6,160 lin.ft. | 30 75 | 189,420 00 | 36 00 | 281,760 00 | 40 00 | 246,400 00 | 30 00 | 184,800 00 | 28 00 | 172,480 00 | 17 00 | 104,720 00 | 25 00 | 154,000 00 | 50 00 | 311,696 00 | 22 00 | 135,520 00 | | |
| 19 | Timbering Section "D" (Alternate) | 445 MBM. | 35 00 | 15,575 00 | 80 00 | 35,600 00 | 150 00 | 66,750 00 | 70 00 | 31,500 00 | 45 00 | 20,025 00 | 50 00 | 22,250 00 | 90 00 | 40,050 00 | 92 00 | 40,940 00 | 60 00 | 26,700 00 | | |
| 20 | Tunnel Section "E" Alternate | 400 lin.ft. | 30 75 | 12,300 00 | 36 00 | 14,400 00 | 40 00 | 16,000 00 | 30 00 | 12,000 00 | 29 00 | 11,600 00 | 16 00 | 6,400 00 | 25 00 | 10,000 00 | 57 50 | 23,000 00 | 25 00 | 10,000 00 | | |
| 21 | Liner Plates (1/8") for Sec. "C" (AH) | 400 lin.ft. | 15 00 | 6,000 00 | 12 00 | 4,800 00 | 10 00 | 4,000 00 | 12 00 | 4,800 00 | 13 00 | 5,200 00 | 10 00 | 4,000 00 | 15 00 | 6,000 00 | 20 00 | 11,500 00 | 15 00 | 6,000 00 | | |
| 22 | Extra thickness of liners for Sec. "C" (AH) 69,000 lbs. | .08 | 4,800 00 | .065 | 3,900 00 | .10 | 6,000 00 | .08 | 4,800 00 | .10 | 6,000 00 | .07 | 4,200 00 | .10 | 6,000 00 | .105 | 6,900 00 | .12 | 7,200 00 | | | |
| 23 | Drain 8" complete | 1800 lin.ft. | 1 20 | 2,160 00 | 3 00 | 5,400 00 | 3 00 | 5,400 00 | .65 | 1,170 00 | 1 50 | 2,700 00 | .75 | 1,350 00 | 2 00 | 3,600 00 | 2 30 | 4,140 00 | 1 10 | 1,980 00 | | |
| 24 | Drain 12" complete | 1,900 lin.ft. | 2 00 | 3,800 00 | 4 00 | 7,600 00 | 3 00 | 5,700 00 | 1 00 | 1,900 00 | 2 00 | 3,800 00 | 1 25 | 2,375 00 | 2 25 | 4,275 00 | 2 60 | 4,940 00 | 2 00 | 3,800 00 | | |
| 25 | Drain 15" Complete | 1,900 lin.ft. | 2 00 | 5,320 00 | 4 50 | 8,550 00 | 3 50 | 6,650 00 | 1 50 | 2,850 00 | 2 50 | 4,750 00 | 1 75 | 3,325 00 | 2 15 | 5,225 00 | 2 95 | 5,415 00 | 3 50 | 6,650 00 | | |
| 26 | Drain 18" complete | 2,000 lin.ft. | 3 50 | 7,000 00 | 5 00 | 10,000 00 | 4 00 | 8,000 00 | 2 00 | 4,000 00 | 3 00 | 6,000 00 | 2 50 | 5,000 00 | 3 25 | 6,500 00 | 3 15 | 6,300 00 | 4 50 | 9,200 00 | | |
| 27 | Overhaul for additional distance | 20,000 Cu.yds. | .02 | 400 00 | .03 | 600 00 | .05 | 1,000 00 | .01 | 20,100 00 | .03 | 600 00 | .002 | 40 00 | .05 | 1,000 00 | .03 | 600 00 | .02 | 400 00 | | |
| 28 | Concrete tunnel lining in place | 6,500 Cu.yds. | 19 00 | 123,500 00 | 26 00 | 169,000 00 | 20 00 | 130,000 00 | 15 00 | 97,500 00 | 20 00 | 130,000 00 | 20 00 | 130,000 00 | 28 00 | 182,000 00 | 21 00 | 142,025 00 | 20 00 | 130,000 00 | | |
| 29 | Concrete Shaft lining in place | 50 Cu.yds. | 19 00 | 950 00 | 50 00 | 2,500 00 | 40 00 | 2,000 00 | 30 00 | 1 | | | | | | | | | | | | |

$$A - 5 - 8 = 14$$

100

Diffuser
14412

End of Lining
Sta. 75+44

LONGITUDINAL TUNNEL SECTION

SHOWING LOCATION OF DIFFUSE

Scale:- $\frac{1}{50}$ " = 1'-0"

OUTLET
8 REQUIRED

Scale: 3" = 1'-0"

extra Strong Black Pipe -

DIFFUSER DETAILS

Scale: $\frac{1}{2}$ " = 10

CITY OF BELLINGHAM, WASHINGTON

DETAIL OF


AMMONIA DIFFUSER


NOV 1 1959

BAER AND CUNNINGHAM


379-L-12

NOV. 1, 1959 BANK AND COMPTONSHAM
A-5-8-14 379-L-12
1463






24 F2



30 F



Attachment B
Defect Coding, Scoring, and Rehabilitation Priority

Appendix B

Defect Coding, Scoring, and Rehabilitation Priority

Presented herein is a discussion of some of the key tunnel liner defect coding definitions relative to the defects encountered in the Lake Whatcom tunnel. Also included is a discussion of defect coding, an example calculation of how segments of the tunnel lining were rated, and a discussion of liner rehabilitation priority. At the end of this appendix is a table listing the defect codes and their relative scoring or weighting.

C.1 Tunnel Liner Defect Coding

The NASSCO PACP method consists of structural and operational type defects that are weighted and then are scored. The types of defects used in this inspection are discussed below.

C.1.1 Structural Defect Coding Definitions

There are two categories of defects: structural and operational. Structural defects generally result in rehabilitation of the liner result in maintenance of the liner. Key structural defects are defined below.

C.1.1.1 Fractures

A fracture is a crack that is open more than 0.015 inch wide and is sometimes accompanied by deformation or evidence of infiltration. It is challenging to differentiate a crack on the interior of the liner from fractures when the fractures are closed. If inspection methods are used that are suited for only above the flow line, fractures below the flow line may not be detected unless the pipe is fully dewatered. There are several types of typical fractures. Fractures observed in the Lake Whatcom tunnel include: longitudinal, circumferential, and diagonal.

C.1.1.2 Cracks

A crack is a defect in the liner that is closed at the surface. The distinction between cracks and fractures is necessary so that consecutive inspection data can be used to determine the progress of deterioration. There are several types of cracks that are typically observed. Fractures in the Lake Whatcom tunnel include: longitudinal, circumferential, and diagonal.

C.1.1.3 Hole

The classification of a hole is used if the defect in the liner wall is less than 12 inches in diameter or if it is rectangular in shape less than 12-inch by 12-inches or equivalent area. A hole in a liner generally warrants repair, particularly if there is evidence of infiltration or migration of fines from behind the line.

C.1.1.4 Surface Damage

Surface damage to a liner occurs on the inner portion of the liner and is caused by chemical attack, biological attack or wear. For a concrete tunnel liner, surface damage includes spalling of the material, and or exposure and corrosion of the reinforcement.

C.1.2 Operational Defect Coding Definitions

Operational defects generally result in the maintenance of the liner. The primary operational defects identified as part of the investigation are defined below.

C.1.2.1 Debris

Debris is a deposit of soils, rock, or other materials that may disrupt flow. If debris consists of construction-related materials, it may be an indication that a more severe condition may exist upstream. A reduction in tunnel or pipe diameter is used to determine severity. This was not an issue in the Lake Whatcom tunnel.

C.1.2.2 Infiltration

Infiltration is the ingress of groundwater into a tunnel or pipe through a defect. Mineral deposits on the liner often indicate infiltration. Infiltration can disrupt the stability of the mass behind the liner.

C.2 Defect Scoring or “Weighting”

NASSCO PACP identifies the scoring of the liner as a rating system and uses a numerical grading system to define the severity of each pipe defect. Defect severity grades for structural defects and operation and maintenance (O&M) defects are assigned by NASSCO PACP based on the risk of further deterioration or failure. The numerical scores or “weights” rank defects on a scale of 1 to 5, with 1 being best (least risk) and 5 being worst (highest risk). A table summary of these scores are presented at the end of this appendix.

C.3 Example Calculation for Liner Rating

PACP uses several methods for scoring the condition of the liner: segment grade scoring, overall pipe rating, structural pipe rating, O&M pipe rating, structural pipe rating index, O&M pipe rating index, and overall pipe rating index. All methods offer their own unique approach for characterizing the condition of the liner. The overall pipe rating index was used for representing the condition of the Lake Whatcom tunnel liner on a per-100-foot segment basis.

The overall pipe rating index is an expression of the defect severity found in the pipe over a 100-foot segment of the tunnel. The index is calculated scoring each defect then adding up the total score. The total is then divided by the number of defects encountered in a defined 100-foot segment. As an example, a pipe segment from Stations 1+00 to 2+00 contains the following defects and associated scores:

1. 5 circumferential cracks = 5 (PACP assigns a score of 1 to each circumferential crack)
2. 2 circumferential fractures = 6 (PACP assigns a score of 3 to each circumferential fracture)
3. 3 longitudinal cracks = 6 (PACP assigns a score of 2 to each longitudinal crack)
4. The sum of defects between Stations 1+00 to 2+00 = 17, calculated by adding 5 + 6 + 6
5. The total number of defects in the 100 foot segment = 10, calculated by adding 5 + 2 + 3

Therefore, in this example the overall pipe rating index for the liner between Stations 1+00 and 2+00 is 2, which is calculated by dividing 17 by 10 and rounding up to 2.

C.4 Rehabilitation Priority

The scores calculated for each 100-foot tunnel segment, as described in the example above, are a rehabilitation priority. NASSCO has established a priority for rehabilitation efforts based on calculated scoring for each segment of the liner. The rehabilitation ranges from “immediate” where the liner has failed, to “not required” where the tunnel is in good or excellent condition. Timelines associated with the rehabilitation priority range from immediate to more than 10 years, depending on the defect(s).

Rehabilitation efforts may include everything from replacing the liner to simply monitoring observed defects over time. Rehabilitation priority and timing is presented in the below.

Rehabilitation Priority from NASSCO PACP

| Condition Rating | Implication | Rehabilitation Priority | Recommended Timing |
|------------------|--|-------------------------|--------------------|
| 5 | Failed or failure imminent | Immediate | — |
| 4 | <ul style="list-style-type: none">Very poor conditionHigh structural risk | High | 1 year |
| 3 | <ul style="list-style-type: none">Poor conditionModerate structural risk | Medium | 5 years |

Rehabilitation Priority from NASSCO PACP

| Condition Rating | Implication | Rehabilitation Priority | Recommended Timing |
|------------------|--|-------------------------|--------------------|
| 2 | <ul style="list-style-type: none">• Fair condition• Minimal structural risk | Low | 5 to 10 years |
| 1 or 0 | Good or excellent condition | not required | >10 years |

Defect Code Summary Table

| Defect Group Name | Defect Group Code | Defect Weight | Group |
|-------------------------------------|-------------------|---------------|-------------|
| Access Point Blind Shaft | ABS | 1 | Operational |
| Access Point Cleanout | ACO | 1 | Operational |
| Access Point Discharge Point | ADP | 1 | Operational |
| Access Point Drift Tunnel | ADT | 1 | Operational |
| Access Point Junction Box | AJB | 1 | Operational |
| Access Point Meter | AM | 1 | Operational |
| Access Point Manhole | AMH | 1 | Operational |
| Access Point Other Special Chamber | AOC | 1 | Operational |
| Access Point Drill Hole (< 3') | APDH | 1 | Operational |
| Access Point Shaft Hole (3' or >) | APSH | 1 | Operational |
| Access Point Tee Connection | ATC | 1 | Operational |
| Access Point WW Access Device | AWA | 1 | Operational |
| Access Point Wet Well | AWW | 1 | Operational |
| Pipe Failure Broken | B | 5 | Structural |
| Brickwork Displaced | BDB | 5 | Structural |
| Brickwork Dropped Invert | BDI | 5 | Structural |
| Brickwork Missing | BMB | 4 | Structural |
| Brickwork Missing Mortar | BMM | 3 | Structural |
| Broken Soil Visible | BSV | 5 | Structural |
| Broken Void Visible | BVV | 5 | Structural |
| Crack | C | 1 | Structural |
| Crack Angular | CA | 2 | Structural |
| Crack Circumferential | CC | 1 | Structural |
| Crack Longitudinal | CL | 2 | Structural |
| Crack Multiple | CM | 3 | Structural |
| Crack Spiral | CS | 2 | Structural |
| Deposits Attached Encrustation | DAE | 1 | Operational |
| Deposits Attached Grease | DAGS | 1 | Operational |
| Deposits Attached Ragging | DAR | 1 | Operational |
| Deposits Attached Other | DAZ | 1 | Operational |
| Deformed Brick | DB | 5 | Structural |
| Deposits Ingress Fines Silt/Sand | DNF | 1 | Operational |
| Deposits Ingress Gravel | DNGV | 1 | Operational |
| Deposits Ingress Other | DNZ | 1 | Operational |
| Deformed Pipe | DP | 5 | Structural |
| Deposits Settled Hard/Compacted | DSC | 1 | Operational |
| Deposits Settled Fine | DSF | 1 | Operational |
| Deposits Settled Gravel | DSGV | 1 | Operational |
| Deposits Settled Other | DSZ | 1 | Operational |
| Fracture | F | 3 | Structural |
| Fracture Angular | FA | 3 | Structural |
| Fracture Circumferential | FC | 3 | Structural |
| Fracture Longitudinal | FL | 4 | Structural |
| Fracture Multiple | FM | 4 | Structural |
| Fracture Spiral | FS | 4 | Structural |
| Geologic Feature | GF | 1 | Other |

| Defect Group Name | Defect Group Code | Defect Weight | Group |
|---|-------------------|---------------|-------------|
| Pipe Failure Hole | H | 2 | Structural |
| Hole Soil Visible | HSV | 4 | Structural |
| Hole Void Visible | HVV | 4 | Structural |
| Infiltration Dripper | ID | 1 | Operational |
| Infiltration Gusher | IG | 1 | Operational |
| Infiltration Runner | IR | 1 | Operational |
| Intruding Seal Material Grout | ISGT | 1 | Operational |
| Intruding Seal Material Sealing Ring | ISSR | 1 | Operational |
| Intruding Seal Material Other | ISZ | 1 | Operational |
| Infiltration Weeper | IW | 1 | Operational |
| Joint Angular | JA | 2 | Structural |
| Joint Offset | JO | 3 | Structural |
| Joint Separated | JS | 4 | Structural |
| Line Down | LD | 1 | Other |
| Lining Failure Abandoned Connection | LFAC | 1 | Other |
| Lining Failure Blistered | LFB | 1 | Other |
| Lining Failure Buckled | LFBK | 1 | Other |
| Lining Failure Service Cut Shifted | LFCS | 1 | Other |
| Lining Failure Detached | LFD | 1 | Other |
| Lining Failure Defective End | LFDE | 1 | Other |
| Lining Failure Overcut Service | LFOC | 1 | Other |
| Lining Failure Undercut Service | LFUC | 1 | Other |
| Lining Failure Wrinkled | LFW | 1 | Other |
| Lining Failure Other | LFZ | 1 | Other |
| Line Left | LL | 1 | Other |
| Line Left/Down | LLD | 1 | Other |
| Line Left/Up | LLU | 1 | Other |
| Line Right | LR | 1 | Other |
| Line Right/Down | LRD | 1 | Other |
| Line Right/Up | LRU | 1 | Other |
| Line Up | LU | 1 | Other |
| Miscellaneous Camera Underwater | MCU | 1 | Other |
| Miscellaneous Direction Change | MDC | 1 | Other |
| Miscellaneous General Observation | MGO | 1 | Other |
| Miscellaneous General Photograph | MGP | 1 | Other |
| Miscellaneous Joint Length Change | MJL | 1 | Other |
| Miscellaneous Lining Change | MLC | 1 | Other |
| Miscellaneous Material Change | MMC | 1 | Other |
| Miscellaneous Repair Recommendation | MRR | 1 | Other |
| Miscellaneous Survey Abandoned | MSA | 1 | Other |
| Miscellaneous Dimension/Diam/Shape Change | MSC | 1 | Other |
| Miscellaneous Survey End | MSE | 1 | Other |
| Miscellaneous Survey Start | MSS | 1 | Other |
| Miscellaneous Tunnel Condition - Fair | MTC | 1 | Other |
| Miscellaneous Tunnel Condition - Good | MTG | 1 | Other |

| Defect Group Name | Defect Group Code | Defect Weight | Group |
|--|-------------------|---------------|-------------|
| Miscellaneous Tunnel Condition - Poor | MTP | 1 | Other |
| Miscellaneous Water Level | MWL | 1 | Other |
| Miscellaneous Water Mark | MWM | 1 | Other |
| Miscellaneous Dye Test | MY | 1 | Other |
| Obstacles/Obstructions Brick or Masonry | OBB | 1 | Operational |
| Obstacles/Obstructions Object Thru Connection | OBC | 1 | Operational |
| Obstacles/Obstructions Object Protruding Thru Wall | OBI | 1 | Operational |
| Obstacles/Obstructions Object Wedged in Joint | OBJ | 1 | Operational |
| Obstacles/Obstructions Pipe Material in Invert | OBM | 1 | Operational |
| Obstacles/Obstructions Construction Debris | OBN | 1 | Operational |
| Obstacles/Obstructions External Pipe/Cable In Sewr | OBP | 1 | Operational |
| Obstacles/Obstructions Rocks | OBR | 1 | Operational |
| Obstacles/Obstructions Built Into Structure | OBS | 1 | Operational |
| Obstacles/Obstructions Other Objects | OBZ | 1 | Operational |
| Obstacles/Obstructions Drop Pipe | ODP | 1 | Operational |
| Roots Ball | RB | 1 | Operational |
| Roots Fine | RF | 1 | Operational |
| Roots Medium | RM | 1 | Operational |
| Point Repair Localized Lining | RPL | 1 | Other |
| Point Repair Patch Repair | RPP | 1 | Other |
| Point Repair Pipe Replaced | RPR | 1 | Other |
| Point Repair Other | RPZ | 1 | Other |
| Roots Tap | RT | 1 | Operational |
| Settlement | S | 1 | Structural |
| Surface Damage Aggregate Missing | SAM | 4 | Operational |
| Surface Damage Aggregate Projecting | SAP | 3 | Operational |
| Surface Damage Aggregate Visible | SAV | 3 | Operational |
| Surface Damage (Metal Pipes) Corrosion | SCP | 3 | Operational |
| Surface Damage Missing Wall | SMW | 5 | Operational |
| Surface Damage Reinforcement Corroded | SRC | 5 | Operational |
| Surface Damage Roughness Increased | SRI | 1 | Operational |
| Surface Damage Reinforcement Visible | SRV | 5 | Operational |
| Surface Damage Surface Spalling | SSS | 2 | Operational |
| Surface Damage Other | SZ | 1 | Operational |
| Tap Break-In/Hammer | TB | 1 | Other |
| Tap Factory Made | TF | 1 | Other |
| Tap Saddle | TS | 1 | Other |
| Vermin Cockroach | VC | 1 | Other |
| Vermin Rat | VR | 1 | Other |
| Vermin Other | VZ | 1 | Other |

| Defect Group Name | Defect Group Code | Defect Weight | Group |
|------------------------------|-------------------|---------------|------------|
| Weld Failure Circumferential | WFC | 4 | Structural |
| Weld Failure Longitudinal | WFL | 5 | Structural |
| Weld Failure Multiple | WFM | 5 | Structural |
| Weld Failure Spiral | WFS | 5 | Structural |
| Collapse Brick | XB | 5 | Structural |
| Collapse Pipe | XP | 5 | Structural |

Attachment C
Inspection Plan

Inspection Plan for Lake Whatcom Screenhouse, Tunnel and Gatehouse

Date: February 16, 2024

Project name: Raw Water Intake - Condition Assessment and Inter-Tie Design

Author: Jacobs Inspection Team

1. Introduction

The purpose of this memorandum is to present the inspection plan for the City of Bellingham's Lake Whatcom Screenhouse, Tunnel and Gatehouse (above-grade portion) facilities. This inspection is a key element in assessing the condition of the raw water supply system. The 72-inch diameter wood-stave intake pipeline upstream of the Gatehouse, in Lake Whatcom, was inspected in December 2023.

The inspection of the Tunnel, Screenhouse, and Gatehouse is planned for March 20, 2024, beginning at 7am and will continue over the course of the day for up to and estimated 11 hours. The results of the inspection will be documented in subsequent reporting that will identify and describe defects and present approaches and estimated costs for rehabilitation.

In support of the inspection effort, the City of Bellingham (City) will close and lock out the slide gate at the Gatehouse at the upstream end of the tunnel in the late evening/early morning prior to the inspection. Shutting the water off will leave the tunnel free of water and available for the inspection team. The City will also lock out the traveling screens within the Screenhouse to provide safe access and avoid any mechanical movement for the Screenhouse assessment team. Once the Screenhouse inspection has been completed and the inspection team is out of the tunnel, the City will open the slide gate at the Gatehouse to re-establish supply to its downstream water treatment plant. The total duration the City estimates it can discontinue water supply is approximately 24 hours.

This inspection plan addresses the following key topics:

- Background Description of Screenhouse, Tunnel and Gatehouse
- Inspection Methods and Approach
- Key Inspection Activities and Chronology
- Inspection and Safety Team
- Equipment Requirements
- Safety Concerns

2. Background Description of Screenhouse, Tunnel and Gatehouse

The Lake Whatcom Gatehouse, Tunnel, and Screenhouse are part of the City's raw water infrastructure that convey water from Lake Whatcom to the City's Whatcom Falls Water Treatment Plant. Each was constructed circa 1939. Upstream of these three infrastructure elements is the 72-inch diameter wood stave intake pipeline (Raw Water Intake) in Lake Whatcom. Downstream of the Screenhouse are large-diameter pipelines that convey raw water to the Water Treatment Plant. This supply system operates

continuously and is very infrequently shutdown, for short durations, for inspection, repair, or regular maintenance.

Screenhouse. The function of the Screenhouse facility has changed over time. At the time of construction, in 1939, the facility served as the primary treatment facility for all municipal water consisting of screening (two traveling screens) and chemical dosing. Following construction of the City's Whatcom Falls Water Treatment Plant in 1966, , the Screenhouse continued to serve the important function of debris-screening. It also served up until the early 2000s as a chlorine injection point. Chlorine injection has since been decommissioned.

Lake Whatcom Tunnel. The tunnel has a design capacity of 98 mgd, is approximately 7,560 feet long, and is constructed through sedimentary rock consisting primarily of shale. Record drawings indicate the tunnel was constructed using drill and blast methods forming a 6.5 foot horseshoe shape and has a cast-in-place concrete lining. The upstream invert elevation of the intake pipe is at 298.5 feet above sea level, and the downstream invert at the screening plant is at 290.94. The tunnel slopes at a uniform rate of 0.1%.

The function of the tunnel is to convey raw water from the Gatehouse at Watkins Point on the West shore of Lake Whatcom near the intersection of Lakeway Drive and Lake Whatcom Boulevard, westward 1.5 miles to the Screenhouse in Whatcom Falls Park on Silver Beach Road. The tunnel entrances at the east and west end will be used in the field inspection and they will provide emergency access. An intermediate access point at Euclid Park, on Euclid Road, will be used as an access point for emergency rescue services, as needed, as well as a lunch break point for the tunnel inspection team.

Gatehouse. The Gatehouse consists of an above grade structure above a wet well caisson. The primary function of the Gatehouse is connecting the 72-inch diameter wood-stave intake pipeline in Lake Whatcom to the Lake Whatcom tunnel with a slide gate for isolation between the two. The Slide gate is integral to the wet well caisson below the Gatehouse. The above grade consists of an empty room, a sampling well and access to the caisson.

3. Project Health and Safety Approach

The inspection for the Screenhouse, Tunnel and Gatehouse will be performed in conformance with the overall Project Health, Safety and Environment (HSE) Plan developed for this project. These planning elements conform with Jacobs' standard safety protocols for confined space entry (CSE), which conform to applicable federal, state, and local requirements. These standard safety protocols, which form the backbone of the safety planning for this work are presented as Attachment A. Also developed for this specific CSE inspection event on March 20, 2024, is an activity-specific safe systems of work (SSOW) plan describing the activities, tools, risks and mitigation measures specific to confined space entry, as well as the Jacobs CSE permit to be used. This SSOW is presented in Attachment B.

4. Inspection Methods and Approach

Two concurrent inspection teams shall be deployed with one inspection team assessing the Screenhouse and above grade portion of the Gatehouse facility and the other, the tunnel inspection team, assessing the tunnel. Both teams will begin their inspection from the Screenhouse facility and perform their respective assessments, as described in the subsections below. The tunnel inspection will begin at the downstream end of the tunnel (Screenhouse) and proceed to the upstream end of the tunnel (Gatehouse). A full list of assessment equipment, including responsible party, is included below in Section 7.

4.1 Screenhouse Inspection

The Screenhouse inspection will include an evaluation of the overall structure (visual) and key components of the facility with particular emphasis placed on condition of the contents within the wet well caisson of the Screenhouse and three 48" outlet pipes from this wet well caisson. The inspection team will include the following subject matter focus areas and individuals performing the inspection:

- Structural Engineer – Bin Ge
- Corrosion Engineer – Cody Nelson
- Slide gates and traveling screens – Aaron George
- Pipe Condition Assessment – Kenny Moffat

In addition to the subject matter experts, additional team member on site will include:

- Phil Martinez (Jacobs, Project Manager) will provide overall project context to the team and will support the inspection.
- Robert Martin and Reece Kurre will be part of the tunnel inspection team with Kenny Moffat.
- Mike Sinon (Jacobs, Health and Safety Manager) will act as the overall confined space supervisor for the inspection effort.
- Life Rescue Inc. will act in the role as on-site standby confined space rescue personnel and will provide harnesses, fall arrest systems, tripods and other confined space entry PPE as appropriate.

The inspection of the screen well, outlet well and the 48" discharge pipes will be conducted via confined space entry. To facilitate the confined space entry, a segmented ladder will be rented and assembled to avoid reliance on the existing, original wall-installed ladder rungs. An image of the ladder segments to be assembled is provided in **Figure 1**.

Prior to beginning entry, the City will lockout-tagout (LOTO) the traveling screens and supplemental dewatering will be completed, as needed, to provide for safe access for the inspection teams.



Figure 1: Segmented Ladder to Support Confined Space Entry

4.2 Tunnel Inspection

The tunnel assessment will be comprised of visual and non-destructive inspection methods. Tunnel defects will be documented using a combination of paper notes and electronic forms capable of generated PDF reports. Photographs will also be taken to document conditions in the tunnel. The alignment of the tunnel and the access portals are as shown below in Figure 2. Note that all access portals will require confined space entry protocols to be in place.




Figure 2: Raw Water Intake Tunnel Alignment and Access Points

The inspection will generally follow industry accepted practices and standards defined by the National Association of Sewer Service Companies (NASSCO) for documenting defects. This inspection will duplicate the inspection work completed in 2015 by CH2M HILL and specific attention will be given to defects identified during the 2015 inspection. As part of the 2015 inspection, stationing anchors were installed at 100 ft intervals to support the orientation of inspection and repair teams during subsequent entries. This inspection will make use of these stationing anchors and observe their condition. In addition to visually identifying and documenting, the inspection will include the following specific tasks:

- Identify changes in the tunnel lining material and/or geometry, if any, from that observed during the 2015 inspection.
- Perform hammer sounding of lining to determine void or separation from rock in locations where visual indications suggest this may be occurring.
- Identify locations of water infiltration either through weep holes constructed for that purpose (if any) or through defects in the lining.
- If observed, document location and extents of previous injection grouting efforts and any other point repairs observed.

Technical Memorandum

The inspection team will make continuous measurement of distance from the tunnel entrance at the Screen House by use of walking-wheel and markings applied by lumber crayon or chalk on the tunnel wall. The inspection team is comprised of the following individuals and roles.

- Lead Tunnel Engineer – Robert Martin
- Support Tunnel Engineer – Reece Kurre
- Pipe Condition Assessment and Rehab – Kenny Moffat

4.3 Gatehouse Inspection

As part of the plant shutdown to allow for the Screenhouse and tunnel inspections, the City will begin by lowering the manual gate in the Gatehouse. Prior to beginning the tunnel or screenhouse inspections, the entrants will lock a chain around the manual gate operator as part of the LOTO procedure.

The Gatehouse inspection will commence following completion of the Screenhouse and will be performed by the individuals identified in the preceding section. This portion of the Gatehouse inspection will be focused on the superstructure and not include the wet well caisson, which was inspected as part of the Raw Water Intake in December 2023. This portion of the inspection is anticipated to be completed during the early afternoon of March 20 and will focus primarily on structural observation.

The tunnel inspection team, upon completion of the tunnel inspection, will exit through the access hatch on the downstream side of the Gatehouse isolation slide gate. The setup for the confined space use of the access hatch is shown in Figure 3 below. This team will document notable observations, as appropriate, on the downstream side of the caisson. The tunnel inspection team is anticipated to be completed in the late afternoon/early evening. Following safe extraction of the tunnel inspection team and equipment, the City will be notified, and the tunnel team locks on the isolation gate will be removed allowing for the gate to be lifted and the treatment plant to go back into service.

Technical Memorandum



Figure 3: Confined Space Entry at Gatehouse

5. Key Inspection Activities and Chronology

The Screenhouse, Tunnel and Gatehouse inspections will be conducted on Wednesday, March 20th, 2024. The key activities associated with the inspections are presented below:

1. January 25, 2024 – Conducted a preliminary safety meeting to outline roles and responsibilities for safety and for inspection with representatives from Jacobs, the City, and Life Rescue.
2. March 5, 2024 – City of Bellingham to conduct dry-run of tunnel gate closure and tunnel drain down with the intent of understanding presence of leaks and drawdown needs in advance of the March inspection.
3. Week of March 11th, 2024 – Segmented ladder sections to be delivered by Brand Safway to the Screenhouse, received by City, and hoisted into the above-grade traveling screen room where the two access hatches are located. Ladders to be assembled on-site, in the two access hatches by Life Rescue, morning of March 20th to facilitate confined space entry.
4. March 14, 2024 – Pre-Inspection meeting between Jacobs, City, and Life Rescue Inc. to share any last-minute information and confirm all needs are in place prior to inspection team arriving on-site.
5. March 20, 2024 (~12 AM until Completion of Tunnel Inspection) – City to close manual slide gate at Gatehouse and take water treatment plant offline. City to open Gatehouse and Screenhouse hatches and turn on fans at both locations to support ventilation of tunnel. City personnel are to maintain a presence at the Gatehouse until the completion of the Tunnel Inspection to observe the gate is functioning as intended and continuous ventilation is directed into the tunnel.
6. March 20, 2024 (6 AM) – Jacobs and Life Rescue personnel arrive on-site to Screenhouse, with City provided access, to begin assembly of segmented ladder to support confined space entry (CSE) within Screenhouse.
7. March 20, 2024 (7 AM) – Full inspection team and safety personnel meet outside in front Screenhouse for 30-minute safety meeting before entry to Screenhouse and beginning inspections.
8. March 20, 2024 (~7:30 AM) – Final tie off ladders at Screenhouse and assemble tripods to support CSE at Screenhouse. Insert gas monitors to begin taking readings and confirm safe environment for entry.
9. March 20, 2024 (~8 AM) – Locks to be placed at traveling screens and at Gatehouse. Once LOTO has been completed, CSE equipment is in place, and confined space entry supervisor (Mike Simon) has confirmed spaces are safe to enter, the Screenhouse and Tunnel inspections will commence.
10. March 20, 2024 (~12 PM) – Anticipated end of Screenhouse inspection. Locks to be removed from traveling screens. Ladder to be removed from the downstream portion of the Screenhouse wet well caisson (downstream of the traveling screens). Following removal of ladder, to be relocated by the City of Bellingham and assembled at Euclid Park for use by Tunnel Inspection Team. Inspection team to head to Gatehouse to complete Gatehouse inspection. At completion of Screenhouse inspection team confined space activity, the Screenhouse inspection team lock at the Gatehouse may be removed; the tunnel inspection team lock is to remain in place.

Technical Memorandum

11. March 20, 2024 (~12:30 PM to 1:30 PM) – Tunnel Inspection team anticipated to arrive at Euclid Park intermediate access portal for lunch break. Two Life Rescue staff shall be available at that time at that location. One City staff person will also need to be at this location at this time.
12. March 20, 2024 (~3PM) – Gatehouse inspection team completes assessment. Life Rescue CSE support team will remain in place and awaits arrival of tunnel inspection team.
13. March 20, 2024 (~5PM) – Tunnel inspection team arrives at Gatehouse and exits tunnel, terminating inspection activities.
14. March 20, 2024 (~5:05PM) – Once communication from Gatehouse confirming the tunnel inspection team is out of the tunnel, Life Rescue Inc. removes fan and lighting. Then, Life Rescue removes remaining segmented ladder from upstream side of the wet well caisson at the Screenhouse following end of tunnel inspection. At least two persons from Life Rescue need to be at this location for this activity and at least one person from the City. Life Rescue to move the segmented ladder to the first floor of Screenhouse.
15. March 20, 2024 (~5:05PM) – At intermediate access portal location in Eclipse Park, once communication from Gatehouse confirming the tunnel inspection team is out of the tunnel, Life Rescue Inc. removes remaining segmented ladder access portal shaft. Two Life Rescue team members need to be at this location for this activity and at least one person from the City. Life Rescue returns segmented ladder to first level at Screenhouse.
16. March 20, 2024 (~5:30PM, or as determined by City) – Lock for Tunnel inspection team to be removed from gate stem at Gatehouse and City of Bellingham staff to open gate and commence activities to restart water treatment plant.
17. Week of March 25th, 2024 – City to provide access to Brand Safway at Screenhouse for pickup of segmented ladder.

6. Inspection Team

The technical inspection team will be comprised of representatives from Jacobs. Life Rescue Inc. will support the technical inspection team with confined-space entry support. Jacobs' regional safety manager shall serve as the Confined Space Supervisor. Roles and designations are shown below in Table 1. For a complete discussion of safety activities planned for this inspection, refer to the project health and safety plan in Attachment 1. Topics included in the health and safety plan include the safety equipment list, confined space entry procedures, activity hazard analysis, and safe systems of work (SSOW).

Table 1: Inspection Team

| Role (Organization) | Name (Contact) |
|--|------------------------------|
| City Site Contact (City of Bellingham) | Steve Day (360 778 7944) |
| Project Manager and Site Lead (Jacobs) | Phil Martinez (425 736 8861) |
| Condition Assessment and Rehabilitation Lead (Jacobs) | Kenny Moffat (360-319-1535) |
| Confined Space Supervisor, Site Field and Safety Lead (Jacobs) | Mike Sinon (406 559 0891) |
| Corrosion Assessment (Jacobs) | Cody Nelson |

Technical Memorandum

| | |
|--|-------------------------------|
| Structural Engineer (Jacobs) | Bin Ge (425.283.7055) |
| Senior Tunnel Engineer (Jacobs) | Robert Martin (414 379 0808) |
| Tunnel Engineer (Jacobs) | Reece Kurre |
| Slide Gate and Traveling Screen (Jacobs) | Aaron George (206 -247 -9814) |
| Standby Rescue Services Lead (Life Rescue) | Kyle Dungan (360-969-7274) |

7. Equipment Requirements

Equipment and instrument requirements for inspection activities can generally be characterized as facilitating (access, lighting, LOTO, and safety) equipment and inspection equipment.

Facilitating equipment includes items that are necessary to allow the inspection team to safely perform their inspections. A list of facilitating equipment (and the anticipated quantity), as well as the responsible party, is provided below in Table 2.

Table 2: Facilitating Equipment and Responsible Party

| Equipment | Responsible Party |
|---|--------------------------------------|
| Confined Space Entry | |
| Tripods with Self-Retracting Lifeline (3) | Life Rescue Inc. |
| Calibrated 4-/5-Gas Monitors (5) | Life Rescue Inc. |
| Segmented Ladder (80 ft) | Brand Safway (Coordinated by Jacobs) |
| Full Body Harness (8) | Life Rescue Inc. |
| Ventilation Fans (2, one each at SH & GH) | City of Bellingham |
| Lockout-Tagout | |
| Equipment Chains/Decommissioning | City of Bellingham |
| Locks | Jacobs |
| Supplemental Access Support | |
| Lights at Screenhouse | City of Bellingham |
| PPE (All Staff) | |
| High Visibility Vests | Jacobs/Life Rescue |
| Hard Hats | Jacobs/Life Rescue |
| Safety Glasses | Jacobs/Life Rescue |
| Gloves | Jacobs/Life Rescue |
| Tyvek Suits (Optional) | Jacobs |
| Hearing Protection (Tunnel Inspection Team) | Jacobs |
| First Aid Kit (1 per Inspection Team) | Jacobs |
| Safety Toed Boots | Jacobs/Life Rescue |

Inspection equipment includes items for carrying out the assessment of the City assets. A list of Inspection equipment and the responsible party is provided below in Table 3.


Table 3: Inspection Equipment and Responsible Party

| Equipment | Responsible Party |
|-------------------------------|-------------------|
| Screenhouse Assessment | |


Technical Memorandum

| | |
|---|--------------------|
| Ultrasonic thickness Gauge | Jacobs |
| Copy of 2014 Screenhouse Assessment and plan Drawings | Jacobs |
| Pit Depth Gauge | Jacobs |
| Tape Measure | Jacobs |
| Chalk | Jacobs |
| Rock Hammer | Jacobs |
| Note Taking Materials | Jacobs |
| Plastic Bag and Permanent Marker | Jacobs |
| Camera | Jacobs |
| Tunnel Assessment | |
| Sounding Hammer | Jacobs |
| Headlamps | Jacobs |
| Chalk | Jacobs |
| Radio | Jacobs/Life-Rescue |
| Rock Hammer | Jacobs |
| Tape Measure/Walking Wheel | Jacobs |
| Lunch/Water | Jacobs |
| Note Taking Materials | Jacobs |
| Plastic Bag and Permanent Marker | Jacobs |
| Camera | Jacobs |
| Gatehouse Assessment | |
| Rock Hammer | Jacobs |
| Note Taking Materials | Jacobs |
| Camera | Jacobs |


Attachment D
Lake Whatcom Tunnel Defect Distribution



PLAN - STA 0+00 TO STA 26+00



PLAN - STA 26+00 TO STA 52+00



PLAN - STA 53+00 TO STA 75+50

LEGEND

REHABILITATION PRIORITY

IMMEDIATE

HIGH

 MEDIUM

LOW

DEFECT SYMBOL

DEFECT SYMBOLS (NEW DEFECTS IDENTIFIED DURING THE 2024 CONDITIONS ASSESSMENT ARE SHOWN IN RED)

○ FRACTURE LONGITUDIN

△ FRACTURE MULTIP

FRACTURE SPIR

X HOLE SOIL VISIB

⊕ HOLE VOID VISIE

TUDINA

PLE

L

E

E

(UPDATED MARCH 2024)

LAKE WHATCOM TUNNEL DEFECT DISTRIBUTION

STA 0+00 TO STA 75+54

Attachment E
Summary of Locations of Holes and Voids
Contributing to High Priority Rating

Attachment E

Summary of Location of Holes and Voids Contributing to High Priority Rating

The specific locations of hole defects within the 100-foot segments contributing to the "high" rehabilitation priority are presented in the table below. Highlighted in purple are the new locations where holes were observed during the March 2024 inspection.

| Station Start | Station End | Hole Defect Observed | Newly Observed in March 2024 |
|----------------------|--------------------|-----------------------------|-------------------------------------|
| 0+96 | 0+96 | Hole Void Visible | |
| 5+47 | 5+49 | Hole Soil Visible | X |
| 15+32 | 15+33 | Hole Void Visible | |
| 15+39 | 15+40 | Hole Void Visible | |
| 16+28 | 16+28 | Hole Void Visible | |
| 16+72 | 16+74 | Hole Soil Visible | |
| 16+97 | 16+98 | Hole Soil Visible | |
| 18+50 | 18+50 | Hole Soil Visible | |
| 19+95 | 19+98 | Hole Soil Visible | |
| 22+60 | 22+61 | Hole Soil Visible | |
| 24+32 | 24+34 | Hole Soil Visible | |
| 25+04 | 25+15 | Hole Void Visible | |
| 25+05 | 25+05 | Hole Void Visible | |
| 25+05 | 25+05 | Hole Void Visible | X |
| 27+40 | 27+43 | Hole Soil Visible | |
| 27+82 | 27+82 | Hole Void Visible | |
| 32+92 | 32+97 | Hole Soil Visible | X |
| 33+90 | 33+96 | Hole Void Visible | |
| 34+56 | 34+57 | Hole Void Visible | |
| 36+18 | 36+21 | Hole Soil Visible | |
| 36+84 | 36+84 | Hole Void Visible | X |
| 38+68 | 38+68 | Hole Void Visible | |
| 42+96 | 43+02 | Hole Void Visible | |
| 44+00 | 44+05 | Hole Soil Visible | |
| 45+12 | 45+12 | Hole Void Visible | |
| 47+59 | 47+59 | Hole Soil Visible | |
| 47+96 | 47+96 | Hole Soil Visible | |
| 48+21 | 48+22 | Hole Soil Visible | |
| 48+23 | 48+23 | Hole Void Visible | |
| 49+09 | 49+09 | Hole Void Visible | |
| 49+09 | 49+09 | Hole Void Visible | X |
| 49+60 | 49+60 | Hole Void Visible | |
| 50+40 | 50+40 | Hole Void Visible | |
| 50+47 | 50+47 | Hole Void Visible | |
| 50+50 | 50+50 | Hole Void Visible | |
| 50+60 | 50+60 | Hole Void Visible | |
| 50+61 | 50+61 | Hole Soil Visible | |

| Station Start | Station End | Hole Defect Observed | Newly Observed in March 2024 |
|---------------|-------------|----------------------|------------------------------|
| 50+67 | 50+67 | Hole Void Visible | |
| 50+97 | 50+97 | Hole Soil Visible | |
| 51+06 | 51+10 | Hole Void Visible | |
| 57+32 | 57+32 | Hole Void Visible | |
| 58+20 | 58+20 | Hole Soil Visible | |
| 59+17 | 59+17 | Hole Void Visible | |
| 59+23 | 59+23 | Hole Void Visible | |
| 61+73 | 61+75 | Hole Soil Visible | |
| 62+75 | 62+75 | Hole Void Visible | |
| 62+78 | 62+78 | Hole Void Visible | X |
| 62+87 | 62+87 | Hole Void Visible | X |
| 62+96 | 62+96 | Hole Void Visible | |
| 63+25 | 63+25 | Hole Soil Visible | |
| 64+52 | 64+53 | Hole Soil Visible | |
| 67+38 | 67+44 | Hole Void Visible | X |
| 70+11 | 70+11 | Hole Void Visible | X |
| 72+59 | 72+60 | Hole Void Visible | |
| 72+64 | 72+64 | Hole Void Visible | |
| 75+11 | 75+14 | Hole Void Visible | |



Technical
Memorandum

1100 – 112th Ave NE, Suite 500
Bellevue, WA 98004
425.453.5000

Attachment F
Tunnel Inspection Reports

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---|---|-------|---|-----|-----|--------------------------|----|-----------------|----------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 0 | 0 | Miscellaneous Survey Start | | | | | | | | | Survey start at 9:05 | | |
| 0 | 0 | Miscellaneous Lining Change | | | | | | | | | Cast in place concrete | | |
| 0 | 0 | Miscellaneous Dimension/Diam/Shape Change | | | | 6.5 | 6.4 | | | | Modified Horseshoe | | |
| 0 | 0 | Access Point Other Special Chamber | | | | | | | | | Screen House | | |
| 0 | 0 | Deposits Settled Other | | | | | 12 | | | | Sand and gravel at invert. | | |
| 0 | 0 | Surface Damage Aggregate Visible | Surface Damage Mechanical Aggregate Visible | | | | | 6 | 6 | | In trough at invert | | |
| 14 | 14 | Obstacles/Obstructions Built Into Structure | | | | | | 6 | | New | Plug in invert | | |
| 16 | 17 | Infiltration Dripper | | | | | | 4 | 4 | | | | |
| 16 | 17 | Fracture Longitudinal | | | | 0.3 | | 4 | 4 | | | | |
| 17 | 17 | Fracture Circumferential | | | | | .2 | 11 | 5 | New | | | |
| 17 | 17 | Fracture Angular | | | | | .3 | 11 | 5 | | | | |
| 22 | 22 | Obstacles/Obstructions Built Into Structure | | | | | | 6 | | New | Plug in invert | | |
| 35 | 35 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 66 | | | Plug in Invert | | |
| 43 | 47 | Fracture Angular | | | | .3 | | 8 | 7 | | | | |
| 45 | 45 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 8 | 8 | | Plug | | |
| 46 | 49 | Fracture Angular | | | | .3 | | 8 | 7 | | | | |
| 46 | 46 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 7 | 7 | | Plug | | |
| 55 | 55 | Fracture Angular | | | | .2 | | 7 | 9 | | | | |
| 56 | 58 | Fracture Angular | | | | .2 | | 3 | 6 | | | | |
| 78 | 84 | Fracture Angular | | | | .3 | | 3 | 5 | | | | |
| 80 | 80 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 3 | 3 | | Plug | | |
| 96 | 103 | Fracture Angular | | | | .3 | | 3 | 4 | | | | |
| 96 | 96 | Infiltration Dripper | | | | | | 12 | 12 | | | | |
| 96 | 96 | Hole Void Visible | | 1 | | | | 12 | 12 | | Hole | | |
| 100 | 122 | Fracture Angular | | | | .1 | | 3 | | New | | | |
| 100 | 102 | Fracture Angular | | | | .25 | | 9 | 11 | New | | | |
| 101 | 101 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 3 | 3 | New | Plug | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---|----------|-------|---|---|------|--------------------------|----|-----------------|---------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 101 | 101 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 3 | | | Plug | | |
| 125 | 125 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 5 | 5 | | Plug | | |
| 125 | 125 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 12 | 12 | | Plug | | |
| 138 | 138 | Obstacles/Obstructions Object Protruding Thru W | | .75 | | | | 3 | 12 | 12 | Steel Pipe | | |
| 140 | 149 | Fracture Angular | | | | | .3 | | 9 | 7 | 2 | | |
| 146 | 146 | Infiltration Runner | | | | | | 9 | 7 | New | | | |
| 202 | 208 | Fracture Spiral | | | | | .2 | | 9 | 4 | | | |
| 206 | 209 | Fracture Angular | | | | | .125 | | 9 | 6 | | | |
| 209 | 220 | Fracture Angular | | | | | .2 | | 3 | 6 | | | |
| 235 | 270 | Fracture Longitudinal | | | | | .3 | | 7 | 7 | | | |
| 240 | 241 | Infiltration Runner | | | | | | 3 | | | 0.25 gpm. | | |
| 240 | 241 | Lining Failure Other | | | | | | 3 | 3 | | Honeycomb | | |
| 245 | 290 | Fracture Longitudinal | | | | | .3 | | 3 | 4 | | | |
| 250 | 250 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 260 | 260 | Infiltration Dripper | | | | | | 12 | 12 | | | | |
| 263 | 263 | Infiltration Dripper | | | | | | 12 | 12 | | | | |
| 325 | 355 | Infiltration Weeper | | | | | | 7 | | New | | | |
| 325 | 355 | Fracture Longitudinal | | | | | .2 | | 7 | 7 | | | |
| 325 | 328 | Fracture Angular | | | | | .1 | | 10 | 7 | | | |
| 327 | 370 | Infiltration Weeper | | | | | | 3 | 4 | | | | |
| 327 | 370 | Fracture Longitudinal | | | | | .2 | | 3 | 4 | | | |
| 338 | 339 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 360 | 368 | Fracture Circumferential | | | | | .1 | | 1 | 6 | | | |
| 501 | 501 | Infiltration Gusher | | | | | | 4 | 4 | | 0.25 gpm | | |
| 508 | 509 | Lining Failure Other | | | | | | 5 | 5 | | Honeycomb | | |
| 508 | 509 | Infiltration Weeper | | | | | | 5 | 5 | | From honeycomb | | |
| 547 | 549 | Hole Soil Visible | | | | | | 6 | 24 | 12 | 12 | | |
| | | | | | | | | | | New | g. vis, soft conc.; liner missi | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|----------------------------------|----------|-------|---|---|-----|--------------------------|----|-----------------|------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 580 | 580 | Infiltration Weeper | | | | | | 5 | 5 | | | | |
| 598 | 603 | Fracture Angular | | | | | .25 | 6 | 9 | | | | |
| 598 | 598 | Fracture Circumferential | | | | | .2 | 3 | 9 | New | | | |
| 603 | 603 | Infiltration Weeper | | | | | | 3 | | New | | | |
| 603 | 607 | Fracture Longitudinal | | | | | .1 | 3 | | New | | | |
| 730 | 730 | Infiltration Weeper | | | | | | 1 | 5 | | Along cold joint | | |
| 749 | 760 | Fracture Longitudinal | | | | | .1 | 7 | 7 | | | | |
| 760 | 760 | Fracture Circumferential | | | | | .2 | 7 | 10 | | | | |
| 760 | 760 | Infiltration Weeper | | | | | | 7 | 10 | | | | |
| 785 | 820 | Fracture Longitudinal | | | | | .3 | 7 | 7 | | | | |
| 785 | 820 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 830 | 830 | Fracture Circumferential | | | | | .1 | 7 | 5 | | | | |
| 843 | 850 | Fracture Angular | | | | | .1 | 8 | 7 | | | | |
| 864 | 864 | Infiltration Dripper | | | | | | 11 | 1 | | | | |
| 864 | 864 | Fracture Circumferential | | | | | .1 | 11 | 5 | | | | |
| 899 | 915 | Fracture Longitudinal | | | | | .1 | 9 | 9 | | | | |
| 899 | 915 | Infiltration Weeper | | | | | | 9 | 9 | | | | |
| 899 | 915 | Fracture Longitudinal | | | | | .1 | 3 | 3 | | | | |
| 900 | 900 | Miscellaneous General Photograph | | | | | | | | 5 | | | |
| 946 | 946 | Fracture Circumferential | | | | | .1 | 7 | 9 | | | | |
| 947 | 1089 | Fracture Longitudinal | | | | | .2 | 3 | 3 | | | | |
| 947 | 1089 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 947 | 948 | Fracture Angular | | | | | .1 | 1 | 3 | | | | |
| 950 | 970 | Fracture Longitudinal | | | | | .3 | 7 | 7 | | | | |
| 1028 | 1041 | Fracture Longitudinal | | | | | .1 | 5 | 5 | | | | |
| 1028 | 1028 | Fracture Circumferential | | | | | .1 | 11 | 5 | | | | |
| 1028 | 1028 | Infiltration Weeper | | | | | | 9 | 3 | New | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|----------|-------|---|-----|---|--------------------------|----|-----------------|---------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 1055 | 1066 | Fracture Longitudinal | | | | .1 | | 7 | 7 | | | | |
| 1060 | 1060 | Infiltration Weeper | | | | | | 7 | 8 | | | | |
| 1060 | 1060 | Fracture Circumferential | | | | .1 | | 7 | 10 | | | | |
| 1061 | 1066 | Fracture Angular | | | | .1 | | 3 | 5 | | | | |
| 1082 | 1092 | Fracture Angular | | | | .1 | | 7 | 9 | | | | |
| 1091 | 1103 | Fracture Angular | | | | .2 | | 1 | 4 | | | | |
| 1091 | 1127 | Infiltration Weeper | | | | | | 7 | 8 | | | | |
| 1091 | 1127 | Fracture Longitudinal | | | | .3 | | 7 | 8 | | | | |
| 1098 | 1127 | Fracture Longitudinal | | | | .2 | | 3 | 5 | | | | |
| 1103 | 1103 | Infiltration Weeper | | | | | | 4 | 4 | | | | |
| 1114 | 1114 | Fracture Circumferential | | | | .2 | | 7 | 5 | | | | |
| 1114 | 1114 | Infiltration Runner | | | | | | 7 | 5 | | | | |
| 1140 | 1202 | Infiltration Weeper | | | | | | 7 | 8 | | | | |
| 1140 | 1202 | Fracture Longitudinal | | | | 0.3 | | 7 | 8 | | | | |
| 1151 | 1200 | Fracture Longitudinal | | | | 0.3 | | 3 | 5 | | | | |
| 1167 | 1167 | Fracture Circumferential | | | | 0.1 | | 11 | 2 | | | | |
| 1167 | 1167 | Infiltration Weeper | | | | | | 11 | 2 | | | | |
| 1202 | 1247 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 1202 | 1247 | Fracture Longitudinal | | | | 0.1 | | 7 | 7 | | | | |
| 1204 | 1258 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 1204 | 1258 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 1218 | 1218 | Fracture Circumferential | | | | | | 3 | 9 | New | | | |
| 1261 | 1297 | Fracture Longitudinal | | | | 0.2 | | 7 | 9 | | | | |
| 1261 | 1297 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 1270 | 1270 | Fracture Circumferential | | | | | | 6 | 3 | New | | | |
| 1280 | 1301 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 1280 | 1301 | Infiltration Weeper | | | | | | 3 | 3 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|----------|-------|---|-----|-----|--------------------------|----|-----------------|---------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 1283 | 1284 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 1285 | 1285 | Fracture Circumferential | | | | | | 3 | 9 | New | | | |
| 1396 | 1398 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 1396 | 1427 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 1397 | 1418 | Fracture Longitudinal | | | | 0.1 | | 7 | 9 | | | | |
| 1397 | 1418 | Infiltration Weeper | | | | | | 7 | 9 | | | | |
| 1428 | 1458 | Fracture Longitudinal | | | | 0.3 | | 7 | 7 | | | | |
| 1430 | 1471 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 1444 | 1449 | Fracture Angular | | | | 0.1 | | 2 | 3 | | | | |
| 1447 | 1447 | Fracture Circumferential | | | | 0.1 | | 6 | 2 | | | | |
| 1447 | 1447 | Infiltration Runner | | | | | | 11 | 2 | | | | |
| 1470 | 1470 | Infiltration Runner | | | | | | 9 | | New | | | |
| 1506 | 1506 | Infiltration Dripper | | | | | | 11 | 2 | | | | |
| 1532 | 1533 | Hole Void Visible | | | | | 12 | 12 | 5 | | Hole | | |
| 1539 | 1540 | Hole Void Visible | | | | | 4 | 6 | 7 | | Hole | | |
| 1539 | 1540 | Infiltration Gusher | | | | | | 7 | 7 | | 1 gpm | | |
| 1558 | 1558 | Infiltration Dripper | | | | | | 11 | 11 | | | | |
| 1603 | 1636 | Infiltration Weeper | | | | | | 7 | 8 | | | | |
| 1606 | 1636 | Fracture Longitudinal | | | | 0.2 | | 7 | 8 | | | | |
| 1609 | 1609 | Infiltration Weeper | | | | | | 7 | 5 | | | | |
| 1609 | 1641 | Fracture Longitudinal | | | | | 0.1 | 3 | 3 | | | | |
| 1609 | 1609 | Fracture Circumferential | | | | | 0.1 | 7 | 5 | | | | |
| 1628 | 1628 | Hole Void Visible | | | 3 | 4 | 12 | 7 | | | Hole | | |
| 1651 | 1656 | Fracture Longitudinal | | | | 0.1 | | 7 | 7 | | | | |
| 1653 | 1655 | Fracture Circumferential | | | | 0.1 | | 8 | 5 | | | | |
| 1655 | 1706 | Fracture Longitudinal | | | | 0.3 | | 7 | 7 | | | | |
| 1658 | 1663 | Fracture Spiral | | | | | 0.1 | 9 | 5 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---------------------------|------------------------|-------|------|-----|----|--------------------------|----|-----------------|-------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 1672 | 1674 | Hole Soil Visible | Changed from 6" to 10" | | 4 | 10 | 24 | 5 | 5 | 7 | Hole soil visible | | |
| 1675 | 1690 | Fracture Angular | | | | 0.1 | | 3 | 5 | | | | |
| 1691 | 1691 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 1697 | 1698 | Hole Soil Visible | | 2 | 8 | | | 5 | 5 | | Soil visible | | |
| 1698 | 1704 | Fracture Angular | | | 0.1 | | | 3 | 5 | | | | |
| 1703 | 1707 | Fracture Angular | | | 0.1 | | | 5 | 12 | New | | | |
| 1704 | 1726 | Fracture Longitudinal | | | 0.1 | | | 3 | 3 | | | | |
| 1818 | 1875 | Fracture Longitudinal | | | 0.3 | | | 3 | 3 | | | | |
| 1818 | 1875 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 1822 | 1840 | Fracture Longitudinal | | | 0.2 | | | 7 | 7 | | | | |
| 1825 | 1825 | Fracture Circumferential | | | 0.2 | | | 7 | 5 | | | | |
| 1830 | 1831 | Fracture Angular | | | 0.1 | | | 3 | 5 | New | | | |
| 1848 | 1851 | Point Repair Patch Repair | | | | | | 7 | 7 | 8 | | | |
| 1849 | 1853 | Fracture Angular | | | 0.2 | | | 7 | 10 | | | | |
| 1850 | 1850 | Hole Soil Visible | | 8 | 7 | | | 7 | 7 | | Hole soil visible | | |
| 1852 | 1857 | Fracture Longitudinal | | | 0.2 | | | 9 | 9 | | | | |
| 1852 | 1857 | Infiltration Weeper | | | | | | 9 | 9 | | | | |
| 1897 | 1907 | Fracture Angular | | | 0.1 | | | 3 | 5 | | | | |
| 1897 | 1907 | Fracture Angular | | | 0.1 | | | 7 | 10 | | | | |
| 1950 | 1966 | Infiltration Dripper | | | | | | 7 | 2 | | | | |
| 1950 | 1966 | Fracture Circumferential | | | 0.05 | | | 7 | 2 | | | | |
| 1995 | 1998 | Hole Soil Visible | | 2 | 3 | | | 5 | 5 | | Hole soil visible | | |
| 1997 | 1997 | Fracture Circumferential | | 0.1 | | | | 7 | 5 | | | | |
| 1997 | 1997 | Infiltration Weeper | | | | | | 12 | 2 | | | | |
| 2047 | 2135 | Fracture Longitudinal | | | 0.3 | | | 7 | 9 | | | | |
| 2054 | 2058 | Fracture Longitudinal | | | 0.2 | | | 5 | 5 | | | | |
| 2054 | 2093 | Fracture Longitudinal | | | 0.2 | | | 3 | 3 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---------------------------|----------|-------|---|-----|---|--------------------------|----|-----------------|------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 2054 | 2055 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 2062 | 2064 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 2096 | 2103 | Fracture Angular | | | | 0.1 | | 7 | 9 | New | | | |
| 2106 | 2106 | Fracture Circumferential | | | | 0.1 | | 3 | 9 | New | | | |
| 2106 | 2112 | Fracture Angular | | | | 0.1 | | 3 | 5 | | | | |
| 2110 | 2135 | Fracture Longitudinal | | | | 0.3 | | 3 | 4 | | | | |
| 2139 | 2153 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2152 | 2158 | Fracture Angular | | | | 0.1 | | 7 | 8 | | | | |
| 2157 | 2222 | Fracture Longitudinal | | | | 0.2 | | 7 | 8 | | | | |
| 2200 | 2202 | Fracture Angular | | | | 0.5 | | 7 | 8 | | | | |
| 2203 | 2203 | Fracture Circumferential | | | | | | 3 | 8 | New | | | |
| 2215 | 2235 | Fracture Longitudinal | | | | 0.1 | | 3 | 5 | | | | |
| 2260 | 2261 | Infiltration Weeper | | | | | | 7 | 7 | | | | |
| 2260 | 2261 | Hole Soil Visible | | | 1 | 3 | | 7 | 7 | | Void moving soil | | |
| 2305 | 2315 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 2305 | 2305 | Infiltration Dripper | | | | | | 10 | 4 | | | | |
| 2305 | 2305 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 2350 | 2365 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2358 | 2365 | Fracture Angular | | | | 0.1 | | 4 | 5 | | | | |
| 2360 | 2361 | Fracture Angular | | | | 0.2 | | 7 | 8 | | | | |
| 2365 | 2385 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2370 | 2375 | Fracture Angular | | | | 0.3 | | 4 | 5 | | | | |
| 2376 | 2376 | Fracture Circumferential | | | | 0.2 | | 11 | 4 | | | | |
| 2380 | 2420 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 2398 | 2410 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2430 | 2480 | Fracture Angular | | | | 0.3 | | 3 | 5 | | | | |
| 2432 | 2434 | Point Repair Patch Repair | | | 6 | | | 7 | 7 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|-----------------------------------|----------|-------|-----|-----|----|--------------------------|----|-----------------|------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 2432 | 2434 | Hole Soil Visible | | | 2 | 5 | 8 | 7 | | | Hole soil visible | | |
| 2450 | 2450 | Infiltration Dripper | | | | | | 11 | 12 | | | | |
| 2450 | 2450 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 2451 | 2475 | Fracture Longitudinal | | | | 0.4 | | 9 | 9 | | | | |
| 2485 | 2502 | Fracture Longitudinal | | | | 0.2 | | 4 | 4 | | | | |
| 2504 | 2515 | Hole Void Visible | | | 1.5 | 3 | | 7 | 7 | | Hole | | |
| 2505 | 2505 | Lining Failure Other | | | 9 | 9 | | 9 | 9 | | honeycomb, 7" deep | | |
| 2505 | 2505 | Infiltration Runner | | | | | | 12 | 12 | | | | |
| 2505 | 2505 | Hole Void Visible | | | 6 | 3 | | 4 | | | Hole | | |
| 2505 | 2505 | Lining Failure Other | | | 8 | 5 | | 8 | 8 | | 3" honeycomb | | |
| 2505 | 2505 | Hole Void Visible | | | 4 | 4 | | 3 | | | Hole | | |
| 2507 | 2510 | Lining Failure Other | | | 15 | 7 | 24 | 7 | 8 | 8 | sp, honeycomb, multiple fra | | |
| 2512 | 2514 | Pipe Failure Hole | | | | | | 6 | 6 | | invert missing; soil vis | | |
| 2512 | 2512 | Miscellaneous General Observation | | | | | | | | | ssurized water spouts at inv | | |
| 2518 | 2519 | Lining Failure Other | | | | 3 | 3 | | 8 | 8 | | | |
| 2555 | 2565 | Infiltration Runner | | | | | | 12 | 12 | | 0.1 gpm | | |
| 2563 | 2600 | Fracture Longitudinal | | | | 0.1 | | 3 | | 3 | New | | |
| 2564 | 2606 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 2570 | 2598 | Fracture Circumferential | | | | 0.1 | | 3 | 5 | | | | |
| 2598 | 2608 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 2598 | 2608 | Fracture Multiple | | | | 0.2 | | 3 | 3 | | | | |
| 2600 | 2615 | Infiltration Weeper | | | | | | 8 | 8 | | | | |
| 2600 | 2615 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2604 | 2670 | Fracture Longitudinal | | | | 0.3 | | 3 | 5 | | | | |
| 2604 | 2604 | Fracture Angular | | | | 0.2 | | 3 | 3 | 3 | New | | |
| 2618 | 2618 | Infiltration Gusher | | | | | | 11 | 1 | | 0.2 gpm | | |
| 2622 | 2622 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|------------------------|-------|---|-----|---|--------------------------|----|-----------------|-------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 2622 | 2635 | Fracture Longitudinal | | | | 0.1 | | 4 | 4 | | | | |
| 2672 | 2690 | Fracture Longitudinal | | | | 0.1 | | 9 | | New | | | |
| 2696 | 2725 | Fracture Longitudinal | | | | 0.1 | | 9 | 9 | | | | |
| 2699 | 2699 | Infiltration Runner | | | | | | 12 | 12 | | 0.1 gpm | | |
| 2699 | 2793 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 2703 | 2706 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 2732 | 2740 | Fracture Longitudinal | | | | 0.1 | | 8 | 8 | | | | |
| 2740 | 2743 | Hole Soil Visible | | | 1 | 3 | | 7 | 7 | | Migrating fines | | |
| 2747 | 2754 | Fracture Angular | | | | 0.1 | | 7 | 8 | | | | |
| 2758 | 2782 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 2770 | 2776 | Fracture Angular | | | | 0.1 | | 8 | 9 | | | | |
| 2782 | 2782 | Infiltration Gusher | | | | | | 7 | 7 | | 0.3 gpm migrating fines | | |
| 2782 | 2782 | Hole Void Visible | | | 3 | 4 | 4 | 7 | | | Hole | | |
| 2824 | 2830 | Fracture Longitudinal | | | | 0.1 | | 9 | | New | | | |
| 2824 | 2824 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | New | | | |
| 2824 | 2830 | Fracture Longitudinal | | | | 0.1 | | 3 | | New | | | |
| 2842 | 2844 | Fracture Angular | | | | 0.2 | | 7 | 2 | | | | |
| 2846 | 2860 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 2861 | 2861 | Infiltration Gusher | | | | | | 12 | 12 | | 0.5 gpm | | |
| 2878 | 2878 | Infiltration Dripper | | | | | | 11 | 11 | | | | |
| 2880 | 2880 | Infiltration Gusher | | | | | | 1 | 1 | | 0.3 gpm | | |
| 2890 | 2890 | Infiltration Weeper | | | | | | 11 | 5 | | | | |
| 2890 | 2890 | Fracture Circumferential | | | | 0.1 | | 11 | 5 | | | | |
| 2905 | 2920 | Fracture Longitudinal | Change from 0.1 tp 0.2 | | | 0.2 | | 9 | 9 | | | | |
| 2951 | 2952 | Lining Failure Other | | | | | | 9 | 10 | | honeycomb | | |
| 2951 | 2952 | Infiltration Dripper | | | | | | 9 | 10 | | 0.1gpm | | |
| 2953 | 2954 | Lining Failure Other | | | | | | 1 | 2 | | honeycomb | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|------------------------|-------|---|-----|----|--------------------------|----|-----------------|------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 2953 | 2954 | Infiltration Gusher | | | | | | 1 | 2 | | | | |
| 2954 | 3161 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 2976 | 3001 | Fracture Angular | | | | 0.3 | | 7 | 8 | | | | |
| 2980 | 2982 | Fracture Angular | | | | 0.1 | | 8 | 1 | | | | |
| 2999 | 3002 | Fracture Angular | | | | 0.1 | | 7 | 9 | | | | |
| 3003 | 3011 | Fracture Angular | | | | 0.1 | | 7 | 9 | | | | |
| 3011 | 3051 | Fracture Angular | | | | 0.3 | | 8 | 9 | | | | |
| 3045 | 3045 | Lining Failure Other | | | 9 | 7 | 9 | 3 | 3 | 9 | Thin liner, exposed shale | | |
| 3058 | 3080 | Fracture Angular | Change from 0.1 tp 0.2 | | | 0.2 | | 8 | 9 | | | | |
| 3060 | 3085 | Fracture Angular | Change from 0.1 tp 0.2 | | | 0.2 | | 2 | 4 | | | | |
| 3082 | 3109 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 3085 | 3115 | Fracture Longitudinal | | | | 0.2 | | 3 | 4 | | | | |
| 3109 | 3202 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 3132 | 3132 | Infiltration Runner | | | | | | 11 | 12 | | 0.2 gpm | | |
| 3144 | 3152 | Fracture Angular | | | | 0.2 | | 1 | 3 | | | | |
| 3150 | 3154 | Fracture Angular | | | | 0.2 | | 5 | 5 | | | | |
| 3153 | 3203 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 3214 | 3259 | Fracture Longitudinal | | | | 0.3 | | 8 | 8 | | Offset 1/8" | | |
| 3215 | 3255 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | Offset 1/8" | | |
| 3246 | 3247 | Fracture Angular | | | | 0.1 | | 7 | 8 | | | | |
| 3250 | 3250 | Fracture Circumferential | | | | 0.1 | | 9 | 3 | | | | |
| 3250 | 3250 | Infiltration Dripper | | | | | | 9 | 3 | | | | |
| 3251 | 3254 | Fracture Angular | | | | 0.2 | | 7 | 8 | | | | |
| 3256 | 3282 | Fracture Longitudinal | | | | 0.1 | | 3 | 4 | | | | |
| 3262 | 3296 | Fracture Longitudinal | | | | 0.1 | | 8 | 9 | | Offset 1/16" | | |
| 3292 | 3297 | Hole Soil Visible | Change from 5" to 10" | | 2 | 10 | 36 | 5 | 5 | | Hole in invert, soil visible | | |
| 3297 | 3297 | Fracture Circumferential | | | | 0.1 | | 10 | 5 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|-----------------------------------|------------------------|-------|---|-----|-----|--------------------------|----|-----------------|-----------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 3297 | 3301 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 3301 | 3302 | Lining Failure Other | | | | 4 | | 1 | 1 | | soft concrete area | | |
| 3304 | 3310 | Fracture Angular | | | | 0.1 | | 7 | 8 | | | | |
| 3306 | 3307 | Lining Failure Other | | | | 7 | 12 | 10 | 11 | | Thin liner area at crown | | |
| 3306 | 3306 | Lining Failure Other | | | | | 5 | 2 | 2 | | Honeycomb 3/4" | | |
| 3311 | 3321 | Fracture Longitudinal | | | | 0.1 | | 9 | 9 | | | | |
| 3323 | 3325 | Fracture Angular | | | | 0.1 | | 7 | 9 | | | | |
| 3390 | 3396 | Hole Void Visible | | | 1 | 1 | | 5 | 5 | | Invert hole | | |
| 3411 | 3419 | Fracture Angular | Change from 0.1 tp 0.2 | | | 0.2 | | 7 | 9 | | | | |
| 3425 | 3440 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 3440 | 3440 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 3440 | 3440 | Infiltration Dripper | | | | | | 7 | 5 | | | | |
| 3456 | 3457 | Hole Void Visible | | | 2 | 1 | | 7 | 7 | | Invert hole | | |
| 3462 | 3497 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 3497 | 3497 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 3497 | 3503 | Fracture Longitudinal | | | | 0.1 | | 9 | 9 | | | | |
| 3618 | 3621 | Hole Soil Visible | Change from 6" to 10" | | 6 | 10 | 36 | 5 | 5 | | shale fragments, void inver | | |
| 3646 | 3646 | Infiltration Gusher | | | | | | 12 | 12 | | 0.3 gpm | | |
| 3646 | 3646 | Miscellaneous General Observation | | | | | | | | | current time 15:07 | | |
| 3684 | 3684 | Hole Void Visible | | | 6 | 4 | 10 | 3 | | New | Hole | | |
| 3684 | 3684 | Fracture Circumferential | | | | 0.1 | | 12 | 3 | New | | | |
| 3735 | 3735 | Infiltration Gusher | | | | | | 12 | | | | | |
| 3735 | 3735 | Lining Failure Other | | | | 2 | | 8 | 3 | | cold joint with honeycomb | | |
| 3815 | 3819 | Fracture Angular | | | | 0.2 | | 3 | 5 | | | | |
| 3819 | 3862 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 3819 | 3862 | Infiltration Weeper | | | | | | 9 | 9 | | | | |
| 3819 | 3857 | Fracture Longitudinal | | | | | 0.3 | 3 | 3 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|----------|-------|---|-----|-----|--------------------------|----|-----------------|---------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 3845 | 3845 | Fracture Circumferential | | | | | | 4 | 8 | New | | | |
| 3868 | 3868 | Hole Void Visible | | | 2 | 5 | 6 | 7 | 7 | | Invert hole | | |
| 3882 | 3882 | Fracture Circumferential | | | | | | 5 | 7 | New | | | |
| 3897 | 3903 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 3903 | 3903 | Infiltration Runner | | | | | | 10 | 1 | | 0.05 gpm | | |
| 3905 | 3922 | Fracture Longitudinal | | | | 0.1 | | 3 | | New | | | |
| 3952 | 3952 | Fracture Circumferential | | | | 0.1 | | 7 | 3 | | | | |
| 3952 | 3952 | Infiltration Dripper | | | | | | 7 | 1 | | | | |
| 4101 | 4122 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 4105 | 4116 | Fracture Longitudinal | | | | 0.1 | | 8 | 8 | | | | |
| 4106 | 4106 | Fracture Circumferential | | | | 0.2 | | 12 | 5 | | | | |
| 4132 | 4151 | Fracture Longitudinal | | | | 0.1 | | 8 | 8 | | | | |
| 4161 | 4161 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 4161 | 4194 | Fracture Longitudinal | | | | 0.1 | | 9 | 9 | | | | |
| 4163 | 4194 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 4163 | 4192 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 4197 | 4205 | Fracture Longitudinal | | | | 0.1 | | 3 | 4 | New | | | |
| 4218 | 4260 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |
| 4247 | 4250 | Fracture Angular | | | | 0.1 | | 8 | 9 | | | | |
| 4267 | 4267 | Infiltration Gusher | | | | | | 2 | 2 | | 0.2 gpm | | |
| 4267 | 4267 | Lining Failure Other | | | | 1 | | 7 | 5 | | cold joint with honeycomb | | |
| 4267 | 4267 | Infiltration Gusher | | | | | | 10 | 10 | | 0.2 gpm | | |
| 4296 | 4302 | Hole Void Visible | | | 3 | 2 | | 7 | 7 | | Invert hole | | |
| 4303 | 4325 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 4303 | 4325 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 4303 | 4309 | Fracture Longitudinal | | | | 0.1 | | 8 | 8 | | | | |
| 4307 | 4313 | Fracture Longitudinal | | | | | 0.1 | 8 | 8 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---|----------|-------|-----|---|---|--------------------------|----|-----------------|------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 4313 | 4330 | Fracture Angular | | | | | | 7 | 9 | New | | | |
| 4313 | 4313 | Fracture Circumferential | | | | | | 5 | 7 | New | | | |
| 4315 | 4315 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 8 | 8 | New | plug | | |
| 4315 | 4315 | Obstacles/Obstructions Built Into Structure | | | | | | 5 | | New | plug | | |
| 4335 | 4335 | Obstacles/Obstructions Built Into Structure | | | | | | 6 | | New | plug | | |
| 4345 | 4345 | Obstacles/Obstructions Built Into Structure | | | | | | 9 | | | plug | | |
| 4345 | 4345 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 3 | 3 | 2 | plug | | |
| 4345 | 4345 | Obstacles/Obstructions Built Into Structure | | | | | | 6 | | | plug | | |
| 4359 | 4370 | Point Repair Other | | | | | | 7 | 5 | 10 | urethane grout | | |
| 4359 | 4359 | Line Left | | | | | | | | 2 | | | |
| 4375 | 4375 | Access Point Shaft Hole (3' or >) | | 36 | | | | | | | Re-entered tunnel at 15:32 | | |
| 4382 | 4382 | Fracture Circumferential | | | 0.2 | | | 7 | 3 | | | | |
| 4396 | 4396 | Fracture Longitudinal | | | | | | 5 | 7 | | | | |
| 4398 | 4398 | Fracture Circumferential | | | 0.2 | | | 7 | 5 | | | | |
| 4400 | 4405 | Hole Soil Visible | | | 2 | 2 | | 7 | 7 | | Invert hole, migrating fines | | |
| 4402 | 4402 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 4 | 4 | | plug | | |
| 4402 | 4402 | Obstacles/Obstructions Built Into Structure | | 4 | | | | 8 | 8 | | plug | | |
| 4403 | 4403 | Point Repair Other | | | | | | 7 | 7 | | chem grout | | |
| 4404 | 4404 | Obstacles/Obstructions Built Into Structure | | | | | | 9 | | New | Wood plug | | |
| 4405 | 4405 | Infiltration Gusher | | | | | | 7 | 7 | 11 | carrying fines, sand and g | | |
| 4408 | 4408 | Infiltration Gusher | | | | | | 7 | 7 | 12 video | 0.75 gpm | | |
| 4412 | 4412 | Fracture Longitudinal | | | | | | 12 | 5 | New | | | |
| 4449 | 4449 | Infiltration Runner | | | | | | 5 | | New | soils vis | | |
| 4449 | 4449 | Point Repair Other | | | | | | 3 | 5 | | chem grout | | |
| 4453 | 4453 | Obstacles/Obstructions Built Into Structure | | | | | | 3 | | | plug | | |
| 4453 | 4453 | Obstacles/Obstructions Built Into Structure | | | | | | 5 | | | plug | | |
| 4512 | 4512 | Hole Void Visible | | | 3 | 2 | 3 | 2 | | New | Hole | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|--------------------------|----------|-------|---|-----|----|--------------------------|----|-----------------|--------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 4535 | 4535 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 4535 | 4549 | Fracture Longitudinal | | | | 0.1 | | 12 | 12 | | | | |
| 4535 | 4535 | Infiltration Weeper | | | | | | 1 | 5 | | | | |
| 4535 | 4549 | Infiltration Weeper | | | | | | 12 | 12 | | | | |
| 4639 | 4639 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 4759 | 4759 | Hole Soil Visible | | | 3 | 3 | 4 | 5 | 5 | | hole, piping fines sands and | | |
| 4771 | 4771 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 4796 | 4796 | Hole Soil Visible | | | 2 | 1 | 6 | 5 | | | hole, piping fine sand and | | |
| 4821 | 4822 | Hole Soil Visible | | | 2 | 3 | 12 | 5 | | | Invert hole, piping sand grave | | |
| 4823 | 4823 | Hole Void Visible | | | 2 | 1 | 9 | 7 | | | Invert hole | | |
| 4830 | 4830 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 4830 | 4830 | Infiltration Weeper | | | | | | 5 | | | 0.3 gpm | | |
| 4896 | 4896 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | New | | | |
| 4909 | 4909 | Hole Void Visible | | | 2 | 2 | 9 | 7 | | | Invert hole | | |
| 4909 | 4909 | Hole Void Visible | | | 2 | 1 | 2 | | | | Hole | | |
| 4960 | 4960 | Hole Void Visible | | 4 | 1 | 4 | 1 | 6 | | | Invert hole; exfiltration | | |
| 5040 | 5040 | Hole Void Visible | | 1 | | 5 | | 6 | | | Invert hole | | |
| 5047 | 5047 | Hole Void Visible | | 2 | | | 6 | | | | vert hole, extends under sl | | |
| 5050 | 5050 | Fracture Circumferential | | | | 0.2 | | 1 | 5 | | | | |
| 5050 | 5050 | Hole Void Visible | | 2 | | | | 6 | | 12 | vert hole, extends under sl | | |
| 5050 | 5056 | Fracture Angular | | | | 0.2 | | 7 | 9 | | | | |
| 5056 | 5094 | Fracture Longitudinal | | | | 0.3 | | 7 | 9 | | | | |
| 5060 | 5060 | Hole Void Visible | | 2 | | 4 | | 6 | | | Invert hole | | |
| 5061 | 5077 | Fracture Angular | | | | 0.2 | | 7 | 9 | | | | |
| 5061 | 5061 | Fracture Longitudinal | | | | | | 5 | 8 | New | | | |
| 5061 | 5114 | Fracture Longitudinal | | | | 0.2 | | 3 | 5 | | | | |
| 5061 | 5061 | Infiltration Runner | | | | | | 5 | 8 | New | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|-----------------------------------|----------------------|-------|----|-----|----|--------------------------|----|-----------------|------------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 5061 | 5061 | Hole Soil Visible | | 2 | | | | 6 | | | Invert hole pipe sand and gravel | | |
| 5067 | 5067 | Hole Void Visible | | 2 | | 3 | | 6 | | | Invert hole | | |
| 5094 | 5109 | Fracture Longitudinal | | | | 0.3 | | 8 | 8 | | | | |
| 5097 | 5097 | Hole Soil Visible | | | 2 | | 4 | 7 | | | Invert hole piping sand and gravel | | |
| 5106 | 5110 | Hole Void Visible | | | 10 | 6 | 12 | 5 | | | Invert hole | | |
| 5109 | 5112 | Fracture Angular | | | | 0.3 | | 4 | 5 | | | | |
| 5115 | 5125 | Fracture Longitudinal | | | | 0.2 | | 4 | 4 | | | | |
| 5153 | 5153 | Infiltration Dripper | | | | | | 10 | 1 | | | | |
| 5175 | 5175 | Infiltration Runner | | | | | | 10 | 12 | | 0.1 gpm | | |
| 5175 | 5175 | Fracture Circumferential | | | | 0.1 | | 10 | 12 | | | | |
| 5732 | 5732 | Hole Void Visible | | 2 | 1 | | | 6 | | | Invert hole | | |
| 5796 | 5832 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 5801 | 5801 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 5801 | 5801 | Infiltration Dripper | | | | | | 11 | 1 | | | | |
| 5808 | 5857 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 5820 | 5820 | Fracture Circumferential | | | | 0.1 | | 7 | 3 | | | | |
| 5820 | 5859 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 5820 | 5820 | Hole Soil Visible | | 4 | 10 | 9 | 7 | | | | Invert hole piping sand gravel | | |
| 5853 | 5864 | Fracture Longitudinal | | | | 0.2 | | 4 | 4 | | | | |
| 5862 | 5867 | Fracture Angular | | | | 0.1 | | 3 | 4 | | | | |
| 5900 | 5900 | Miscellaneous General Observation | | | | | | | | | current time 17:03 | | |
| 5914 | 5924 | Fracture Longitudinal | | | | 0.1 | | 8 | 8 | | | | |
| 5917 | 5917 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 5917 | 5917 | Hole Void Visible | Change from 2" to 9" | | 2 | 9 | 10 | 7 | | | Invert hole | | |
| 5922 | 5942 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 5923 | 5923 | Hole Void Visible | | | 5 | 6 | | 7 | | | 5" deep void | | |
| 5980 | 6010 | Fracture Longitudinal | | | | 0.2 | | 3 | 3 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|----------------------------------|--|-------|---|-----|---|--------------------------|----|-----------------|-------------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 6000 | 6000 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 6000 | 6000 | Infiltration Dripper | | | | | | 12 | 2 | | | | |
| 6008 | 6133 | Fracture Longitudinal | | | | 0.3 | | 3 | 3 | | | | |
| 6050 | 6065 | Fracture Longitudinal | | | | 0.2 | | 9 | 9 | | | | |
| 6064 | 6090 | Fracture Longitudinal | | | | 0.2 | | 8 | | | | | |
| 6094 | 6100 | Fracture Angular | | | | 0.1 | | 7 | 8 | | | | |
| 6115 | 6115 | Fracture Circumferential | | | | | | 4 | 7 | New | | | |
| 6146 | 6162 | Infiltration Weeper | | | | | | 3 | 3 | | | | |
| 6146 | 6162 | Fracture Longitudinal | | | | 0.2 | | 3 | 5 | | | | |
| 6146 | 6146 | Fracture Circumferential | | | | 0.2 | | 3 | 5 | | | | |
| 6146 | 6146 | Infiltration Weeper | | | | | | 3 | 5 | | | | |
| 6173 | 6175 | Hole Soil Visible | | | 2 | 2 | | 7 | | | Hole piping sand | | |
| 6192 | 6192 | Fracture Circumferential | | | | 0.2 | | 7 | 5 | | | | |
| 6211 | 6284 | Fracture Longitudinal | | | | 0.3 | | 9 | 9 | | Offset 1/16" | | |
| 6212 | 6214 | Fracture Angular | | | | 0.1 | | 12 | 1 | New | | | |
| 6214 | 6328 | Fracture Longitudinal | | | | 0.3 | | 3 | | | Offset 3/16" | | |
| 6250 | 6250 | Surface Damage Aggregate Visible | Surface Damage Chemical Aggregate Projecting | 3 | 8 | | | 3 | | | spalled | | |
| 6275 | 6275 | Hole Void Visible | | 4 | 3 | | | 3 | | 3 | Hole | | |
| 6278 | 6278 | Fracture Circumferential | | | | | | 5 | 9 | New | | | |
| 6278 | 6278 | Hole Void Visible | | 3 | 3 | 4 | 3 | | | New | Hole | | |
| 6280 | 6324 | Fracture Angular | | | | 0.2 | | 7 | 9 | New | | | |
| 6287 | 6287 | Hole Void Visible | | 10 | 7 | 10 | 7 | | | New | Hole | | |
| 6296 | 6296 | Fracture Circumferential | | | | 0.1 | | 8 | 4 | | | | |
| 6296 | 6296 | Hole Void Visible | | 2 | 2 | 5 | 4 | | | New | Hole | | |
| 6325 | 6325 | Hole Soil Visible | | 2 | | 9 | 5 | | | | Hole piping sand gravel shale | | |
| 6452 | 6453 | Hole Soil Visible | Changed from 5" to 7" | 2 | 7 | | | 5 | 5 | | Hole pipe sand and gravel | | |
| 6485 | 6485 | Infiltration Dripper | | | | | | 10 | 12 | | | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|---|----------|-------|----|-----|---|--------------------------|----|-----------------|-------------------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 6485 | 6485 | Fracture Circumferential | | | | 0.1 | | 8 | 4 | | | | |
| 6485 | 6490 | Fracture Angular | | | | | | 12 | 3 | New | | | |
| 6485 | 6490 | Fracture Longitudinal | | | | | | 9 | | New | | | |
| 6490 | 6532 | Fracture Longitudinal | | | | 0.1 | | 3 | 3 | | | | |
| 6490 | 6490 | Fracture Circumferential | | | | | | 5 | 9 | New | | | |
| 6490 | 6507 | Fracture Longitudinal | | | | 0.2 | | 8 | 8 | | | | |
| 6547 | 6547 | Infiltration Dripper | | | | | | 12 | | | | | |
| 6649 | 6649 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | | | | |
| 6649 | 6649 | Infiltration Runner | | | | | | 7 | 5 | | 0.1 gpm | | |
| 6730 | 6770 | Fracture Circumferential | | | | | | 5 | 7 | New | | | |
| 6738 | 6744 | Hole Void Visible | | | 1 | 1 | | 7 | 5 | | Hole | | |
| 7011 | 7011 | Hole Void Visible | | | 1 | 3 | 2 | 5 | | New | Hole | | |
| 7021 | 7021 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | New | | | |
| 7106 | 7106 | Fracture Circumferential | | | | 0.1 | | 7 | 5 | New | | | |
| 7150 | 7150 | Hole Void Visible | | | 1 | 1 | 1 | 5 | 5 | | | | |
| 7259 | 7260 | Hole Void Visible | | | 1 | 2 | | 7 | | | Hole | | |
| 7264 | 7264 | Hole Void Visible | | | 3 | 4 | | 7 | | | 2" deep hole | | |
| 7266 | 7266 | Infiltration Dripper | | | | | | 1 | | | | | |
| 7356 | 7356 | Infiltration Dripper | | | | | | 12 | 1 | | | | |
| 7415 | 7415 | Infiltration Runner | | | | | | 5 | 10 | New | | | |
| 7415 | 7415 | Fracture Longitudinal | | | | | | 5 | 10 | New | | | |
| 7511 | 7511 | Point Repair Patch Repair | | | | | | | | | rec repair | | |
| 7511 | 7514 | Hole Void Visible | | | | | 3 | 11 | | | 7" deep hole, hollow | | |
| 7511 | 7511 | Fracture Circumferential | | | | 0.1 | | 5 | 7 | | | | |
| 7545 | 7545 | Miscellaneous Dimension/Diam/Shape Change | | | 65 | | | | | | flare out to gate house | | |
| 7553 | 7553 | Access Point Shaft Hole (3' or >) | | | 30 | | | | | | Gate house | | |
| 7554 | 7554 | Miscellaneous Survey End | | | | | | | | | current time 18:00 | | |

RECORD COPY

| | |
|------------------|---------------|
| Inspection Date: | 03/20/2024 |
| Start Time: | 0900 |
| End Time: | 1630 |
| Report Number: | 1 |
| Tunnel Number: | 1 |
| Inspector Name: | Robert Martin |

Tunnel Inspection Report For: Lake Whatcom Tunnel

| Inspection Station Start | Inspection Station End | Code | | Value | | | | Circumferential Location | | Image Reference | Remarks | | |
|--------------------------|------------------------|-------------------------------|----------|-------|----|----|---|--------------------------|----|-----------------|------------|--|--|
| | | Descriptor | Modifier | Feet | | | | | | | | | |
| | | | | D | H | W | L | At/From | To | | | | |
| 7554 | 7554 | Access Point WW Access Device | | | 72 | 70 | | | | 4 | slide gate | | |