

Lower Squalicum Habitat Restoration Photo Gallery



Pre-project: Erosion on right bank of Squalicum Creek.



Fish screening installed prior to construction.



Heavy machinery creates notches for LWD that will help redirect streamflow.



LWD placement in left bank.



Drilling holes in LWD to cable wood.



LWD structures embedded in right bank.



Second layer of LWD.



Completed LWD installment, looking downstream.



Completed project at high flow.